

Model	P/N	Mode A Functions		Mode B Functions	
		A1	A2	B1	B2
HSL	HSL-101	GR (S) + WH (FL)	890nm IR (S) + 850nm IR (FL Morse Code 'D' / B+)	890nm IR (FL / D)	890nm IR (FL / B)
	HSL-102	890nm IR (S)	890nm IR (S) + 850nm IR (FL Morse Code 'D' / B+)	890nm IR (FL / D)	890nm IR (FL / B)
	HSL-103	GR (S)	GR (S) + WH (FL Morse Code 'D' / B+)	890nm IR (FL / D)	890nm IR (S) + 850nm IR (FL Morse Code 'D' / B+)

Operating Modes		
Color Code	Signal Type	Signal Intensity
GR = Green	S= Steady	Dim, Standard, Bright, Bright+
WH= White	D= Dim	Bright+ (B+) is significantly brighter than "Bright" (B) Higher intensity shortens battery life
IR= Infrared	FL= Flash (60 fpm)	All White Flash are "Bright" to meet FAA 3 status mile visibility