

Model / Mode	M1	M2
HS-402X	GR (S)	IR (FL)
HS-403X	WH (FL)	GR (S)
HS-404X	WH (FL)	IR (FL)
HS-405X	GR (S) + WH (FL)	GR (S)
HS-406X	IR (FL)	IR (S)
HS-407X	WH (S)	IR (FL)
HS-408X	GR (S)	RD (S)
HS-410X	WH (S)	RD (S)
HS-411X	RD (FL)	IR (S)
HS-412X	WH (S)	GR (S)

Operating Modes		
Color Code	Signal Type	Signal Intensity
GR = Green	S= Steady	Dim, Standard, Bright, Bright+
RD= Red	D= Dim	Bright+ (B+) is significantly brighter than "Bright" (B) Higher intensity shortens battery life
IR= Infrared	FL= Flash (60 fpm)	All White Flash are "Bright" to meet FAA 3 status mile visibility
WH= White	FN= NATO Flash (30 fpm)	