

Model	P/N	Mode A Functions		Mode B Functions	
		A1	A2	B1	B2
F ²	HS-720-101	GR (S/D)	GR (S/D) + WH (FL)	IR (FL/D)	IR (FL/B)
	HS-740-104	GR (S/D)	RD (S/D)	IF (FL)	IR (S/D)
	HS-740-107	GR (S/D)	GR (S/D) + WH (FL)	IR (FL/D)	IR (FL/B+)

Operating Modes		
Color Code	Signal Type	Signal Intensity
WH= White	S= Steady	Dim, Standard, Bright (B), Bright+ (B+)
GR = Green	D= Dim	Bright+ is significantly brighter than "Bright" Higher intensity shortens battery life
RD= Red	FL= Flash (60 fpm)	All White Flash are "Bright" to meet FAA 3 status mile visibility
IR= Infrared	FN= NATO Flash (30 fpm)	