

**Vehicles that are NOT compatible with our cup holder expander selection.**

| <b>Make</b> | <b>Year</b>           | <b>Model</b>               |
|-------------|-----------------------|----------------------------|
| Audi        | 2017-2023             | A4                         |
| Audi        | 2010-2023             | Q5                         |
| BMW         | 2011-2023             | X3 and 3 Series            |
| BMW         | 2009-2023             | 7 Series                   |
| Honda       | 2008-2023             | Accord                     |
| Honda       | 2018-2023             | Odyssey                    |
| Honda       | Any                   | Pilot                      |
| Lexus       | Any                   | GX450                      |
| Lexus       | 1999-2015             | RX350                      |
| Mazda       | 2004-2023             | 3 & CX-5                   |
| Nissan      | 2002-2023             | Xterra                     |
| Subaru      | 2013-2023             | Crosstrek                  |
| Subaru      | 2009-2023             | Forester                   |
| Subaru      | 2015-2023             | Impreza                    |
| Subaru      | 1990-2014 & 2020-2023 | Legacy (Fits 2015 - 2019)  |
| Subaru      | 2005-2014 & 2020-2023 | Outback (Fits 2015 - 2019) |
| Toyota      | 2001-2023             | Highlander                 |
| Toyota      | 2019-2023             | RAV4                       |
| Volvo       | 2003-2023             | XC90                       |

There may be other vehicles that are not compatible that we have not discovered yet. If you have any questions, please contact us at [info@integralusa.net](mailto:info@integralusa.net).

For any vehicles not listed, please also compare your vehicle's cup holders to the photo below:




**1. Close to dashboard**



**2. Raised edges**



**3. Covers or lids**



**4. Odd shaped**