

INSTRUCTION SHEET

Buell
AMERICAN MOTORCYCLES

-J02591

Kit Number 40398-03Y

REV. 01-09-2003

HIGHLIGHTED BUELL XB SPROCKET KIT

General

Kit number 40398-03Y is designed to fit 2003 Buell XB9R and XB9S.

NOTE

Sprocket bolts should be discarded and replaced each time they are removed. Replacement bolts (Part Number AA0609.11CXZB) are available separately from any Buell dealer.

NOTE

A Service Manual for your model motorcycle is available from any Buell dealer.

⚠ WARNING

A Service Manual is necessary for installation of this kit. The rider's safety depends upon the correct installation of this kit. If the procedure is not within your capabilities or you do not have the correct tools, have your Buell dealer perform the installation. Improper installation of this kit could result in death or serious injury.

Installation Notes

Refer to the Cast Rear Wheel section in your Service Manual. Remove the existing sprocket according to Service Manual instructions. Discard the old bolts and washers. Install the new sprocket in the same location using new washers from the kit and new bolts (Part Number AA0609.11CXZB), purchased separately from any Buell dealer.

INSTRUCTION SHEET

Buell
AMERICAN MOTORCYCLES

-J02591

Kit Number 40398-03Y

REV. 01-09-2003

HIGHLIGHTED BUELL XB SPROCKET KIT

General

Kit number 40398-03Y is designed to fit 2003 Buell XB9R and XB9S.

NOTE

Sprocket bolts should be discarded and replaced each time they are removed. Replacement bolts (Part Number AA0609.11CXZB) are available separately from any Buell dealer.

NOTE

A Service Manual for your model motorcycle is available from any Buell dealer.

⚠ WARNING

A Service Manual is necessary for installation of this kit. The rider's safety depends upon the correct installation of this kit. If the procedure is not within your capabilities or you do not have the correct tools, have your Buell dealer perform the installation. Improper installation of this kit could result in death or serious injury.

Installation Notes

Refer to the Cast Rear Wheel section in your Service Manual. Remove the existing sprocket according to Service Manual instructions. Discard the old bolts and washers. Install the new sprocket in the same location using new washers from the kit and new bolts (Part Number AA0609.11CXZB), purchased separately from any Buell dealer.