

Set Up Instructions


BEC-TRIO CURVED


Step 1: Assemble the different frame sections by pushing and pulling pipes together.



Step 3: Align two frames together making sure holes face each other.








over those poles.

Step 6: Align top frame to bottom frame and push support poles into the frame. With some force connect the support poles in the middle to complete.

Step 7: Unzip print and place one frame inside. Position holes on frame to align with eyelets in graphic. Thread cable through eyelet. Repeat for all eyelets.

Step 9: Complete.







Step 8: Zip graphic closed around top of frame. Pull all cables out until inside loop is flush with eyelets. Attach all cables together at a single point for hanging.

