AT HOME INSTRUCTIONS FOR MASKS

WHAT YOU WILL NEED:

-MASK PATTERN (AVAILABLE AT NHAKHANH.COM)

-TIGHLY WOVEN COTTON-BLEND FABRIC

-CUT 2 MASK MAIN

-CUT 1 MASK TOP LINING

-CUT 1 MASK BOTTOM LINING


-11 INCHES OF THING ELASTIC

-5 INCHES OF GROSSGRAIN


-4 INCHES OF BENDABLE METAL (PIPECLEANER, WIRE, METAL)

-BENDABLE WIRE

-NON-WOVEN FILTER



- PLACE 2 MAIN MASK PIECES TOGETHER
- SEW A 2 INCH LINE UP CENTER TOP AND BOTTOM



- FOLD MASK MAIN DOWN CENTER WITH RIGHT SIDES TOGETHER
- CREATE DARTS ON TOP AND BOTTOM


(DARTS WILL BE CURVED TO SIT COMFORTABLY ON NOSE AND MOUTH)



- TURN LINING TO RIGHT SIDE
- PUSH DARTS TO LEFT AND SEW IN PLACE




- CUT 11 INCH ELASTIC IN HALF (5.5 INCHES)
- ON THE RIGHT SIDE, SEW ELASTIC ON MASK MAIN SIDES ¼ IN FROM TOP AND BOTTOM EDGE



- ROLL HEM THE STRAIGHT EDGE OF THE TOP LINING AND BOTTOM LINING PIECES



- WITH RIGHT SIDES FACING UP,
- PLACE THE TOP LINING OVER BOTTOM LINING, MATCHING UP TOP HEM WITH BOTTOM LINING NOTCH AT SIDES



- WITH TOP AND BOTTOM LININGS TOGETHER TOP STITCH 2 INCHES ALONG TOP LINING HEM




- PUT RIGHT SIDES TOGETHER AND CREATE DARTS ON TOP AND BOTTOM LININGS



STEP 9:

- WITH RIGHT SIDES TOGETHER, PLACE MASK MAIN AND TOP/BOTTOM LININGS TOGETHER




STEP 10:

- SERGE ALL OUTTER EDGES TOGETHER



STEP 11:

- TURN RIGHT SIDE OUT
- TOP STITCH ALONG ALL EDGES



- TURN GROSSGRAIN EDGES IN ¼ INCH
- PLACE ALONG TOP EDGE OF MASK
- TOPSTICH ALONG TOP AND BOTTOM EDGE OF GROSSGRAIN
- INSERT BENDABLE METAL



STEP 13:

- INSERT FILTER

