

Shade Tee Repair Schedule

Service	Description	Price
Canopy Frame Replacement	Replacement of damaged or improperly operating canopy frame with new factory frame.	\$30.00
Pole repair – Pole separation	Repair poles that have come apart.	\$20.00
Pole repair – Stake receiver	Replace threaded aluminum stake receiver with new factory stake receiver.	\$20.00
Pole repair – Bent pole	Replacement of bent ShadeTee Pole with new factory pole of same color.	\$50.00
Fabric Canopy	Canopies that have been damaged or worn are easily and quickly replaced self service. Replacement canopies are available from Anderson Golf online. Anderson Golf will replace canopies for customer that prefer canopy replacement as a factory service.	\$40.00
Steel Stake	Steel stakes that are damaged cannot be repaired, however, are available as a replacement part at Anderson Golf Online.	\$14.99-\$16.99
Carry Bags	Carry bags that are damaged or worn cannot be repaired, however, are available as a replacement part at Anderson Golf Online.	\$10.99

Prior to returning a ShadeTee for repair:

- Anderson Golf should be contacted at admin@andersongolfideas.com or 910-724-3412 to have a repair case number assigned.
- Shipping costs for repairs are the responsibility of the customer. Discounted shipping labels will be provided by Anderson Golf.
- Repairs will be sent to Anderson Golf, 80 Blake Blvd #4586, Pinehurst, NC 28374.
- To expedite return of repaired ShadeTees, every effort is made to repair ShadeTees the same day they are received.