



Flange Mount Installation with Mounting Cage

1. Set Mounting Cage into concrete. Leave a minimum of 40mm (1 ½ inch) thread proud of the ground level.
2. Place Fixture flange over the proud bolt threads and tighten using provided nuts and washers.
3. Trim off excess thread once tight. (Additional bolts may be used under the fixture flange to level the fitting. If this is the case be sure to leave sufficient thread proud of ground level.)



1:1 SCALE

WHEN PLOTTING TEMPLATE

Make sure horizontal and vertical dimensions match dimensions labelled on the template

PRINTING

Please Print @ A3 SIZE
WITH "ACTUAL SIZE" SELECTED