

CHICAGO PLENUM / GASKETED ELECTRICAL COVER INSTRUCTIONS FOR LUMINOUS HE FIXTURE

<u>Warning</u>: Before starting any work ensure that all sources of power are turned off. All work must meet local codes and be performed by a certified electrician. Do not mount fixture vertically.



- 1. SECURE CONDUIT TO ACCESS PLATE USING POWER FEED FITTING AND NUT (SUPPLIED BY OTHERS UNLESS PREORDERED).
- 2. SECURE GROUND WIRE TO ACCESS PLATE USING 8-32 HEX CUP SCREW.
- 3 ATTACH REMAINING WIRES ENSURING ALL CONNECTIONS ARE PROPERLY MATCHED.
- 4. PLACE WIRES AND CONNECTORS INTO FIXTURE.



- 5. SECURE ACCESS PLATE TO HOUSING USING ACCESS PLATE SCREW
- 6. ENSURE GASKET IS WRINKLE FREE AND FULLY COMPRESSED.

