

MAXcam 360c Firmware v1.8 Release Notes

What's New in Firmware v1.8

Cedar Electronics is happy to announce the release of version 1.8 firmware for the MAXcam 360c. We have developed several key improvements in this release which should continue to improve your experience with your MAXcam 360c.

Enhancements:

- For situations where the unit was exhibiting power cycling behavior (unit shuts down and restarts on its own), this has been fixed
- For situation where all four arrows were alerting during a K or Ka band alert, this has been fixed
- Improved transition with arrows (front to rear / rear to front)

How to Get the Update

Downloads are available directly to your MAXcam 360c. If you are taking advantage of the Wi-Fi connection in your vehicle or have access to Wi-Fi, you will be prompted for the update once it becomes available. Updates are also available through Drive Smarter.

Manual downloads are available using a USB connection with your PC or Mac if you are unable to utilize either the WiFi or Drive Smarter update directly with your device using our website ([Update Your Device \(escortradar.com\)](http://www.escortradar.com)). If you have any questions, please contact our customer care team at 800-543-1608.

Keep the Feedback Coming

We want to keep hearing from you! If you have feedback or suggestions on how to make the MAXcam 360c even better, send an email to radarfeedback@cedarelectronics.com.