





TIME TO HAVE A LITTLE FUN >>



MINI AK-47 ASSEMBLY GUIDE



PARTS LIST

A. Charging handle

[1] Spring

B. Top handguard

[1] Rod

C. Bottom handguard

[2] Lg screws

D. Muzzle

[2] Md screws

E. Bolt carrier

F. Dust cover

[1] Short screw

[1] Screwdriver

G. Receiver

with magnet

H. Magazine

I. Non-firing rounds

J. Stock

K. Display stand

L. Barrel



Insert top handguard (B) into bottom (C) handguard until firmly seated on both ends.



Insert short screw to bottom of barrel where the holes align.



Push rod through holes in the barrel (L). To get rod flush, you may need to apply force by pushing rod against a solid surface.



Attach muzzle (D) by threading onto the end of barrel.



Screw the two medium-length screws into bottom of receiver to secure barrel in place.



Insert charging handle (A) into receiver (G), handle facing right side. Slide spring [1] onto bolt carrier (E). Insert combined bolt carrier and spring into charging handle, align in rear grooves of receiver (G).

7



Place dust cover (F) over the charging handle (A) by placing the front of the cover forward and push down until it rests in the groove in stock.

8



Attach the stock (J) and tighten top and bottom witht the two large screws.

9



Load non-firing rounds into the magazine (H). Slide magazine in until it clicks into place. Show off your GoatGun on display stand.

