

Linseed Oil Putty is made from our raw linseed oil and various types of chalk. The putty can be used for window frames and to fill holes and cracks outdoors and indoors.

Instructions

- If there is skin on top, remove it.
- Before use, empty out all of the putty in the container and knead until it softens.
 The putty is easier to knead if you warm it first, e.g. in the microwave or on a radiator.
- Once kneaded, the putty can stay out on the table for several days. Leftover putty can be stored in the freezer.
- It is easiest to apply the putty at room temperature. If the putty is too sticky, knead it on a piece of cardboard or add more chalk. If it is too hard, warm it up or add a tiny amount raw oil.
- The edges of the window pane should be free from dirt, paint or any old putty.

- Brush the rebate with shellac before bedding the window pane in place.
 This will prevent the oil from seeping into the wood and will significantly extend the life of the putty.
- Make sure the window pane is properly stabilised and supported to avoid any movement in the rebate.
- Use a soft brush and ground pumice to remove any oil residue from the window pane.
- Paint all of the coats about 2 cm onto the glass.
- You can paint over the putty immediately or later.
- Once the paint is dry, moisten the glass surface with a weak soap and water solution. Cut and straighten the edges of the painted putty with a razor glass scraper and a steel spackling blade as a guide, leaving 2 mm of paint on the window pane. See video online.



Door from 1926. Easy "anti-aging" measure for 100 years. Linseed Oil Putty in cracks. Painting an old surface with new Linseed Oil Paint.

Holes and dry cracks can be filled with putty that can be painted over right away. Mix the putty with a few drops of raw linseed oil and use this thinned putty to temporarily seal cracked rebates, cracks and unsealed corner joints.



Cut the edges of the painted putty in a weak soap and water solution.

Easy to maintain

- Apply thinned putty with a brush and use a rag to wipe away any excess.
- Paint immediately.



Thinned putty – an easy "anti-aging" measure.