


## DIGITAL MINI THERMO-HYGROMETER




We thank you for the purchase of Baldr Digital mini thermo-hygrometer. It has been designed and constructed using innovative components and techniques to enable the perfect display of indoor temperature and humidity by this device. Please read the instructions carefully to become familiar with the properties and functions, before you use the unit.

For the start-up of this device you require:  
1xCR2025 Lithium battery(included)

## OVERVIEW

### MAIN UNIT



1. Comfort level
2. indoor humidity
3. indoor temperature
4. Max/min record of temperature&humidity
5. Change temperature display between °C and °F

## FEATURES

1. Large temperature &humidity display.
2. Temperature range : -4 °F ~122 °F (-20 °C ~+50 °C).
3. Humidity range : 20%-99%.
4. Comfort level indication.
5. °C/°F switchable.
6. Max/min record of temperature&humidity.
7. Low battery indicator.
8. Stand,hang or attach by magnet.
9. Power supply: 1x CR2025 lithium battery (Included).

## GETTING STARTED

### POWER ON

1. Remove the plastic tab from the battery compartment prior to use.
2. The LCD will display all digits and icons for 3 seconds, followed by the temperature&humidity reading.

## TEMPERATURE

1. After power on, the temperature will display automatically.
2. If you want to change between Fahrenheit and Celsius,press "C/F" button.
3. Press"Max/Min"button to check the Max/Min record of temperature ,the checking order is Max,Min temperature,and then auto-return to current temperature 10 seconds later. Press and hold the "Max/Min"button for 2 seconds to clear the max/min records.
4. Temperature display range : -4 °F ~+122 °F (-20 °C ~+50 °C);for temperature lower than -4 °F , the reading will be "LL.L"; for temperature higher than +122 °F , the reading will be "HH.H".
5. When the temperature reading is between 39.2 °F ~46.22 °F (+4 °C ~+7.9 °C ), the icon ❄ will display to indicate the frosting point.
6. Temperature resolution: 0.2 °F (0.1 °C).
7. Temperature accuracy around +/-0.5 °C (+/-0.9 °F )

## HUMIDITY

1. After power on,the humidity will display automatically.
2. Press"Max/Min"button to check the Max/Min record of humidity ,the checking order is Max ,Min humidity and then auto-return to current humidity 10 seconds later. Press and

hold the "Max/Min"button for 2 seconds to clear the max/min records.

3. Humidity display range : 20-99%;for humidity lower than 20% , the reading will be "LL.L"; for humidity higher than 99% ,the reading will be "HH.H"

## COMFORT LEVEL INDICATION

"OK" icon: humidity between 40%RH-70%RH  
"LOW" icon: humidity lower than 40%RH  
"HIGH" icon: humidity higher than 70%RH

## PRECAUTIONS

- Do not clean any part of the product with benzene, thinner or other solvent chemicals. When necessary, clean it with a soft cloth.
- Never immerse the product in water. This will damage the product.
- Do not subject the product to extreme force, shock, or fluctuations in temperature or humidity.
- Do not tamper with the internal components.
- Do not mix new and old batteries or batteries of different types.
- Do not mix alkaline, standard or rechargeable batteries with this product.
- Remove the batteries if storing this product for a long period of time.
- Do not dispose of this product as unsorted municipal waste. Collection of such waste separately for special treatment is necessary.

## WARRANTY

- BALDR provides a 1-year limited warranty on this product against manufacturing defects in materials and workmanship.
- Warranty service can only be performed by our authorized service center. The original dated bill of sale must be presented upon request as proof of purchase to us, or our authorized service center.
- The warranty covers all defects in material and workmanship with the following specified exceptions:(1) damage caused by accident, unreasonable use or neglect (including the lack or reasonable and necessary maintenance); (2) damage occurring during shipment (claims must be presented to the carrier); (3) damage to, or deterioration of any accessory or decorative surface;(4) damage resulting from failure to follow instructions contained in your owner's manual.
- This warranty covers only actual defects within the product itself, and does not cover the cost of installation or removal from a fixed installation, normal set-up or adjustments, claims based on misrepresentation by the seller or performance variations resulting from installation-related circumstances.
- To receive warranty service, the purchaser must contact with BALDR nominated service center for the problem determination and service procedure.
- Thank you for your choice of BALDR products!

www.baldr.com  
service@baldr.com