


For SP1 N camera, the calibration process for bad pixel is below:

1》 Please cover the lens with the lens cap and be sure there is no light leaking into the lens (very important!).


2》 Press UP button and hold it and then press POWER button until the unit comes into FACTORY mode. LCD should show as the following picture:



3》 Press the OK button 2 times. The calibration process for bad pixel will start, and it will take about 20 seconds.



4》 If the calibration is successful, the LCD will show "OK". If not, please redo steps 1-3.



5》 Press POWER button to turn off camera and then press again to turn on.