

When you plug the HD2 into a computer using the supplied USB cable:

1. The screen with 3 choices, MSDC, CHARGE and OPEN will appear.
2. Press the DOWN button (lower button on the side) to highlight CHARGE.
3. Press the OK button (middle button on the side) to put camera into charge mode (LCD screen will turn off).
4. While the battery is charging, the red LED on the top of the camera will be on.
5. When charging is complete, the red LED will go off.