

Tubes for Scattering – Instructions for Use

1. Remove lid from urn by twisting gently.



2. Remove inner (white) tube by twisting gently and place on a flat surface with open end facing upwards.



3. Slowly fill the white tube with cremated remains (using a funnel if required).

4. Squeeze a generous line of glue around the **inside** circumference of the outer tube (the one that has the printed image & has a hole in the base) approximately inch below the rim. Any glue suitable for paper should be suitable.



5. Line up the openings of both tubes and push the outer tube downwards slowly, to allow air to escape through the vent hole.



6. Once the tubes are firmly in place, attach the label provided over the vent hole.



PLEASE NOTE – it is important to attach the label at this point in the assembly to prevent any leakage of remains through the vent hole when the tube is returned to its upright position.

7. Turn the sealed urn over and place the lid on ensuring that any image is aligned.



8. To scatter cremated remains, take the lid off and push out the perforated disc.

