





PLEASE RECYCLE

- EN** Contains: 20 tough butyl rubber plugs
Side of Bacon: 0.125 in. x 2 in. (3.175mm x 50.8mm)
Weight (5 plugs): 1.5g/0.05 oz
- DE** Inhalt: 20 harte Reparaturstreifen aus Butylkautschuk
Side of Bacon: Reparaturstreifen für schlauchlose Reifen - Nachfüllpackung
3,175mm x 50,8mm | Gewicht (5 Reifenreparaturstreifen): 1,5g/0,05 oz
- FR** Contient : 20 bouchons en caoutchouc butyle solides
Side of Bacon: Recharge de bouchons pour pneu sans chambre à air
3,175mm x 50,8mm | Poids (5 bouchons) : 1,5g/0,05 oz
- IT** Contenuto: 20 tappini in robusta gomma butile
Side of Bacon: Ricambio dei tappi per gomme prive di camera d'aria
3,175mm x 50,8mm | Peso (5 tappi): 1,5g/0,05 oz
- ES** Contiene: 20 conectores de goma de butilo resistentes
Side of Bacon: Repuesto de tapón para neumático sin cámara
3.175mm x 50.8mm | Peso (5 tapones): 1,5g/0,05 oz
- NL** Bevat: 20 duurzame pluggen van butylrubber
Side of Bacon: Navulpluggen voor tubeless banden
3.175mm x 50.8mm | Gewicht (5 pluggen): 1,5g/0,05 oz
- PT** Contém: 20 buchas fortes em borracha butílica
Side of Bacon: Reenchimento da válvula sem câmara de ar
3.175mm x 50.8mm | Peso (5 buchas): 1,5g/0,05 oz



Genuine
INNOVATIONS®

ITW Global Tire Repair Inc.

125 Venture Drive, Suite 210, San Luis Obispo, CA 93401 USA

ITW Global Tire Repair Europe GmbH

Carl-Benz Str. 10, 88696, Owingen, Germany +49-7551-9200-0

www.genuineinnovations.com

comments@genuineinnovations.com

Made in China

PART# G20452

10.18.16



7 16281 50907 0