



Declaration of Performance

No.: 07/4A20-4P20
Version: 09-22

- Concrete roof tiles for roofing:
Gredos, Evolution, Teide, Guadarrama, Universal, H-Compact, Plana, Plana Evolution, Arcadia and Superval, Almanzor, Latina, Summum.
- Concrete fittings for roofing:
Ridge, Universal verge, Ventilation tile, Lanterne base tile, Pitched-change tile, eaves tile, eaves tile right and left verge (corner), Right and Left verge, Step tile, Half tile, Eaves half tile, Right end cap, Right and Left end verge (corner), Right end half cap, eaves barrel tile almanzor, barrel right/left verge almanzor, Ridge start, Ridge end, Ornamental ridges (valley saw, pinnacle, totem, etc...), Valley end, 3-4 ridge junctions.

1. UNIQUE IDENTIFICATION CODE OF THE PRODUCT TYPE

07/4A20-4P20

2. INTENDED USE

Concrete roof tiles and fittings for roofing or wall cladding on buildings.

3. MANUFACTURER, and, if applicable, AUTHORIZED REPRESENTATIVE

BMI ROOFING SYSTEMS, S.L.U.
Ctra. Villaluenga-Cobeja, Km 3.5
45520 Villaluenga de la Sagra (Toledo) - Spain
Authorized Representative: N/A

4. SYSTEM OR SYSTEMS AVCP

SYSTEM 3

5. HARMONIZED STANDARD or ETA

EN 490:2011

6. NOTIFIED BODY(IES)

WFRGENT nv
Ottergemsesteenweg-Zuid 711, 9000 Gent, Belgium
Notified Body number: 1173

7. DECLARED PERFORMANCE

Essential Characteristics	Performance	Harmonized technical specification
Mechanical resistance	Complies	EN 490:2011
External Fire Performance*	Broof	
Reaction to fire**	A2-s1, d0	
Water Impermeability	Complies	
Dimensional stability	Complies	
Durability	Complies	

NPD: No performance determined

*in acc. with Commission Decision 2000/553/EC

**in acc. with Commission Decision 96/603/EC

Signed for and on behalf of the manufacturer by:

Mr. Carlos HERNÁNDEZ PUENTE - Managing Director

At Villaluenga de la Sagra

on 15/09/2022

The performance of the product identified in points 1 and 2 is in conformity with the set of declared performance/s in point 7. This declaration of performance is issued, in accordance with Regulation (EU) No 305/2011, under the sole responsibility of the manufacturer identified in point 3.