




STANADYNE & ROOSAMASTER INJECTION PUMPS SALE



STANADYNE & ROOSA MASTER Allis Chalmers - Cummins - GM - John Deere

- ▶ DB2-4101 (C0147046406) | Qty = 5
- ▶ DB2-4195 (C0147046203) | Qty = 8
- ▶ DB2-4197 (C0147046207) | Qty = 6
- ▶ DB2-4322 (C0147046102) | Qty = 5
- ▶ DB2-4347 (C0147046507) | Qty = 3
- ▶ DB2-4348 (C0147046511) | Qty = 1
- ▶ DB2-4351 (C0147046506) | Qty = 2
- ▶ DB2-4373 (C0147046513) | Qty = 4
- ▶ DB2633-4337 (403057060) | Qty = 3
 - ▶ C0147046410 | Qty = 1




NEW

\$450.00
each

Goldfarb & Associates
FIND US ON



STANADYNE & ROOSAMASTER INJECTION PUMPS SALE



STANADYNE & ROOSA MASTER Allis Chalmers - Cummins - GM - John Deere

- ▶ DB2-3973 (22510360) | Qty = 1
- ▶ DB2-4106 (22511745) | Qty = 2
- ▶ DB2435-4615 (RE29003) | Qty = 1
- ▶ DBGFC633-2DH (AT22490T) | Qty = 1
- ▶ DBGFC637-50AJ (AR36877) | Qty = 1
- ▶ DBGFC637-23AL (AR36878) | Qty = 2
- ▶ DBGFC637-13AFR (4020500) | Qty = 1
- ▶ DBGVC631-1DH (AT17626T) | Qty = 3
- ▶ DCGFC627-7JTR (673163C91) | Qty = 1
- ▶ DM4-4745 (RE37513) | Qty = 1
- ▶ DM4629-4316 (RE15734) | Qty = 1

REBUILT

\$450.00
each

Goldfarb & Associates
FIND US ON




WWW.GOLDFARBINC.COM

STANADYNE & ROOSAMASTER INJECTION PUMPS SALE


749750C91 | Qty = 2
AR73509 | Qty = 1
DB2-3778 | Qty = 1
DB2-4212 | Qty = 1
DB2427-4359 | Qty = 5
DB2435-5141 | Qty = 1
DB2-4360 | Qty = 13
DB2-4404 | Qty = 3
DB2-4417 | Qty = 1
DB2-4484 | Qty = 1
DB2-4515 | Qty = 1
DB2-4860 | Qty = 1
DB2-4972 | Qty = 1
DB2-4989 | Qty = 1
DB2627-4260 | Qty = 1
DB2629-4108 | Qty = 2
DB2629-4417 | Qty = 1
DB2825-3271 | Qty = 2
DB2825-3744 | Qty = 2
DB2829-3811 | Qty = 3
DB2829-3926 | Qty = 1
DB2829-3930 | Qty = 1
DB2829-3973 | Qty = 4
DB2829-4369 | Qty = 1
DB2829-4723 | Qty = 1
DB2829-YL4126 | Qty = 2
DB4327-5910 | Qty = 1
DB4327-6049 | Qty = 32
DB4327-6050 | Qty = 5
DB4327-6373 | Qty = 1
DB4429-5731 | Qty = 1
DB4429-6047 | Qty = 14
DB4429-6048 | Qty = 7
DB4429-6155 | Qty = 20

DB4429-6156 | Qty = 2
DB4429-6162 | Qty = 40
DB4435-5865 | Qty = 1
DB4627-4777 | Qty = 4
DB4727-6451 | Qty = 1
DBGFC427-3AP | Qty = 2
DBGFC629-59AE | Qty = 1
DBGFC631-10C | Qty = 1
DBGFC631-1AE | Qty = 2
DBGFC631-20AJ | Qty = 1
DBGFC631-29AL | Qty = 1
DBGFC631-46AJ | Qty = 1
DBGFC631-49AE | Qty = 1
DBGFC631-57AE | Qty = 1
DBGFC633-3LR | Qty = 1
DBGFC637-1 | Qty = 1
DBGFC637-15A | Qty = 1
DBGFC637-31AF | Qty = 3
DBGFC637-33F | Qty = 1
DBGFC637-54AF | Qty = 1
DBGVCC631-4BF | Qty = 1
DBMFC433-1LK | Qty = 1
DCGFC627-9AJ | Qty = 1
DCGFC827-14FB | Qty = 2
DGBFC627-2DH | Qty = 1
DGFCL-427-12M | Qty = 2
DGFCL635-10B | Qty = 1
DGFCL635-7AQ | Qty = 1
DGVCL435-7C | Qty = 1
DM4627-2916 | Qty = 1
DM4629-2935 | Qty = 1
DM4-E4968 | Qty = 1
RE500848 | Qty = 4
RE509003 | Qty = 1



CORES

**\$175.00
each**



Goldfarb & Associates

FIND US ON



WWW.GOLDFARBINC.COM

4972 BOILING BROOK PKWY, ROCKVILLE, MD 20852 | (301) 770-4514