



## Hamaton TPMS Application Chart 2022

This document, and all information contained therein, is the property of Hamaton Inc, and must not be reproduced, cited or distributed without expressed written consent of Hamaton Inc.

Please note: the information included in this document is a reflection of the information available on <https://www.hamaton-tpms.us.com> at the time that it was created. Every effort is made to ensure that the information included is correct, but it cannot be guaranteed. For up-to-date information, always refer to <https://www.hamaton-tpms.us.com>.

**Acura**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
CSX	2008 - 2011	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
CSX	2012 - 2012	VDO TG1C Clamp-In 315 MHz		6-139B*	6-231*
ILX	2012 - 2015	VDO TG1C Clamp-In 315 MHz		6-139B*	6-231*
ILX	2016 - 2018	VDO TG1C Clamp-In 315 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
ILX	2019 - 2022	Continental New Style TG1C Snap-In 433 MHz			6-505
MDX	2004 - 2006	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
MDX	2007 - 2013	Pacific Clamp-In 315 MHz		6-116T*	
MDX	2014 - 2015	VDO TG1C Clamp-In 315 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
MDX	2016 - 2020	VDO TG1C Clamp-In 315 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
MDX	2022 - 2023	Continental New Style TG1C Snap-In 433 MHz			6-505
NSX	2016 - 2022	VDO TG1C Clamp-In 433 MHz		6-140	6-231*
RDX	2007 - 2012	Pacific Clamp-In 315 MHz		6-116T*	
RDX	2013 - 2015	VDO TG1C Clamp-In 315 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
RDX (315Mhz)	2016 - 2019	VDO TG1C Clamp-In 315 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
RDX (433Mhz)	2019 - 2022	VDO TG1C Clamp-In 433 MHz		6-140	6-231*
RL	2005 - 2008	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
RL	2009 - 2013	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
RLX	2014 - 2015	TRW Version 1 Fixed Valve Clamp-In 315 MHz		6-114*	
RLX	2016 - 2022	VDO TG1C Clamp-In 315 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
TL	2005 - 2008	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
TL	2009 - 2013	TRW Version 1 Fixed Valve Clamp-In 315 MHz		6-114*	
TL	2014 - 2014	TRW Version 1 Fixed Valve Clamp-In 315 MHz		6-114*	
TLX	2015 - 2017	VDO TG1C Clamp-In 315 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
TLX	2018 - 2022	VDO TG1C Clamp-In 433 MHz		6-140	6-231*
TSX	2007 - 2008	Pacific Clamp-In 315 MHz		6-116T*	
TSX	2009 - 2014	Pacific Clamp-In 315 MHz		6-116T*	
ZDX	2010 - 2013	TRW Version 1 Fixed Valve Clamp-In 315 MHz		6-114*	

**Alfa Romeo**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
4C	2013 - 2020	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Giulia (Snap-In)	2016 - 2022	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
Giulia (Clamp-In)	2017 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Stelvio (Clamp-In)	2018 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*

**Aston Martin**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
DB11	2016 - 2019	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
DB11	2020 - 2022	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
DB9	2004 - 2018	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
DBS	2007 - 2012	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
DBS Superleggera	2018 - 2022	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Rapide	2010 - 2016	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Rapide S	2014 - 2019	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
V12 Vantage	2009 - 2018	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
V12 Vantage	2022 - 2022	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
V8 Vantage	2006 - 2009	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
V8 Vantage	2010 - 2016	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
V8 Vantage	2017 - 2022	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Vanquish	2012 - 2016	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Vanquish S	2017 - 2018	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Virage	2012 - 2012	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

**Audi**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
A3	2006 - 2010	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
A3	2011 - 2011	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
A4 (B6,B8)	2002 - 2008	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
A4 (B7,B8)	2009 - 2011	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201

## Audi

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
A5	2008 - 2011	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
A6	2002 - 2004	Huf Gen 1.2 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
A6	2005 - 2011	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
A6 Allroad Quattro (433Mhz)	2001 - 2004	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
A6 Allroad Quattro (315Mhz)	2001 - 2005	Huf Gen 1.2 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
A6 Allroad Quattro	2005 - 2009	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
A6 Allroad Quattro	2010 - 2011	HUF Gen 1 Clamp-In -S037 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
A8	2000 - 2003	Huf Gen 1.2 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
A8	2004 - 2010	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
E-tron	2020 - 2023	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Q5	2009 - 2009	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
Q7	2007 - 2009	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Q8	2020 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Q9	2021 - 2021	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
R8 (433Mhz)	2008 - 2022	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
R8 (315Mhz)	2014 - 2018	Huf Gen 2 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
RS3	2017 - 2020	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
RS3 (315Mhz)	2017 - 2018	Huf Gen 3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
RS4	2007 - 2008	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
RS5	2019 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

### Audi

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
RS6	2003 - 2004	Huf Gen 1.2 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
RS6	2021 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
RS7 (433Mhz)	2014 - 2018	HUF Gen 1 Clamp-In -S037 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
RS7 (315Mhz)	2014 - 2018	Huf Gen 2 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
RS7	2021 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
RSQ8	2020 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
S5	2008 - 2011	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
SQ5	2014 - 2016	HUF Gen 1 Clamp-In -S037 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
TT	2008 - 2010	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
TT RS	2018 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

### Bentley

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Arnage	2008 - 2009	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Azure	2006 - 2010	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Bentayga	2017 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Brooklands	2008 - 2011	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Continental GT (Built Before June 2005)	2003 - 2005	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Continental GT (Built After May 2005)	2005 - 2022	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Flying Spur	2006 - 2022	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Mulsanne	2011 - 2020	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

**BMW**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
1 Series (Built Before October 2011)	2008 - 2011	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
1 Series (Built After September 2011)	2011 - 2013	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
2 Series (Built Before April 2014)	2014 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
2 Series (Built After March 2014)	2014 - 2020	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
2 Series	2021 - 2022	Huf Gen 2 Slim Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-240*
3 Series (315Mhz)	1999 - 2002	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
3 Series (433Mhz)	1999 - 2006	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
3 Series	2007 - 2009	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
3 Series	2010 - 2012	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
3 Series (Built Before April 2014)	2013 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
3 Series (Built After March 2014)	2014 - 2019	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
3 Series	2019 - 2023	Huf Gen 2 Slim Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-240*
4 Series (Built After March 2014)	2014 - 2020	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
4 Series (Built Before April 2014)	2014 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
4 Series	2021 - 2023	Huf Gen 2 Slim Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-240*
5 Series	1997 - 2002	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
5 Series	2003 - 2005	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
5 Series (E60, E61 Only)	2006 - 2011	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
5 Series (F10, F07 Only, Built Before March 2014)	2011 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
5 Series (Built After March 2014)	2014 - 2016	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

## BMW

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
5 Series	2017 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
5 Series GT	2017 - 2017	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
6 Series	2003 - 2010	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
6 Series (Built Before April 2014)	2012 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
6 Series (Built After March 2014)	2014 - 2019	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
7 Series (433Mhz)	1994 - 2001	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
7 Series (315Mhz)	2000 - 2001	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
7 Series (E66)	2001 - 2005	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
7 Series (Built before October 2011)	2006 - 2011	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
7 Series (Built after September 2010 and built Before April 2014)	2011 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
7 Series (Built After March 2014)	2014 - 2015	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
7 Series	2016 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
8 Series	2017 - 2023	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Alpina B6	2015 - 2019	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Alpina B7	2004 - 2011	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Alpina B7 (Built Before May 2014)	2012 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Alpina B7 (Built After April 2014)	2014 - 2023	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
i Series (Built After April 2014)	2014 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
M2	2014 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
M3	2002 - 2009	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

## BMW

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
M3	2010 - 2013	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
M3	2015 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
M4	2015 - 2019	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
M4	2020 - 2023	Huf Gen 2 Slim Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-240*
M5 (Built before October 2010 E60 )	2006 - 2010	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
M5 (Built after September 2010 and Built before April 2014)	2010 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
M5 (Built After March 2014)	2014 - 2017	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
M5	2018 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
M6	2006 - 2010	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
M6 (Built before April 2014)	2012 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
M6 (Built after March 2014)	2014 - 2016	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
M6	2017 - 2019	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
M6	2020 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
M7	2019 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
M8	2020 - 2023	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
X1 (E84)	2013 - 2015	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
X1 (F46, F48)	2015 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
X2 (F46, F48)	2018 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
X3 (E83)	2004 - 2010	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
X3 (F12, Built Before April 2014)	2010 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

**BMW**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
X3 (Built After March 2014)	2014 - 2016	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
X3	2017 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
X4 (F26)	2015 - 2018	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
X4 (G02)	2018 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
X5	1999 - 2004	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
X5 (E70)	2006 - 2010	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
X5 (Built Before September 2013)	2011 - 2013	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
X5 (Built After August 2013)	2013 - 2016	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
X5 (F15)	2017 - 2019	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
X5 (F15)	2017 - 2019	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
X5 (G05)	2019 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
X6 (Built Before April 2010)	2008 - 2010	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
X6 (Built Between March 2010 and April 2014)	2010 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
X6 (Built After March 2014)	2014 - 2019	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
X6	2020 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
X7	2019 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Z4 (Built before October 2010)	2002 - 2010	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Z4 (Built after September 2010)	2010 - 2013	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Z4	2014 - 2016	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Z4	2019 - 2022	Huf Gen 2 Slim Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-240*

**Bugatti**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Chiron	2017 - 2022	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Veyron	2009 - 2015	Huf Gen 2 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

**Buick**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Allure	2007 - 2008	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Allure	2009 - 2011	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Cascada	2016 - 2019	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Enclave	2008 - 2008	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Enclave	2009 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Enclave	2016 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Enclave	2018 - 2023	Schrader Snap-in Faraday 433MHz GM Basic TFA 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Encore	2013 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Encore	2016 - 2022	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Encore GX	2020 - 2022	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Encore GX	2020 - 2022	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Envision	2016 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Envision	2018 - 2020	-in Gen6 Faraday GM TFA 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Envision	2021 - 2023	Schrader Gen6 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
LaCrosse	2006 - 2008	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
LaCrosse	2009 - 2009	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
LaCrosse	2010 - 2011	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210

**Buick**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
LaCrosse	2012 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
LaCrosse (433Mhz)	2017 - 2020	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
LaCrosse (433Mhz)	2017 - 2020	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
LeSabre	2007 - 2007	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Lucerne	2007 - 2011	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Rainier (Clamp-In)	2006 - 2007	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Regal (315 Mhz)	2011 - 2019	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Regal (433Mhz)	2018 - 2020	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Regal (433Mhz)	2018 - 2020	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Verano	2012 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Verano	2016 - 2018	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210

**Cadillac**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
ATS	2013 - 2013	VDO TG1D Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
ATS (Snap-In)	2014 - 2015	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
ATS (Clamp-In)	2014 - 2016	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
ATS (Snap-In)	2016 - 2019	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
ATS Performance	2013 - 2013	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
ATS Performance	2014 - 2015	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
ATS Performance	2016 - 2017	Schrader Gen Delta Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
ATS-V	2016 - 2017	Schrader Gen Delta Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235

## Cadillac

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
CT4 (Clamp-In)	2020 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
CT4 (Snap-In)	2020 - 2022	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
CT5	2020 - 2022	Schrader Gen6 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
CT6 (Import)	2017 - 2018	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
CT6 (Import)	2017 - 2018	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
CT6 (315MHz)	2019 - 2020	-in Gen6 Faraday GM TFA 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
CTS	2004 - 2007	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
CTS	2008 - 2011	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
CTS (Clamp-In)	2009 - 2012	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
CTS (Snap-In)	2012 - 2012	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
CTS (Clamp-In)	2013 - 2013	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
CTS (Snap-In)	2013 - 2013	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
CTS (Clamp-In)	2014 - 2019	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
CTS (Snap-In)	2014 - 2015	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
CTS	2016 - 2019	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
CTS-V	2009 - 2015	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
CTS-V	2016 - 2017	Schrader Gen Delta Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Deville	2001 - 2005	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
DTS	2006 - 2006	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
DTS	2007 - 2011	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*

## Cadillac

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
ELR	2014 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
ELR	2016 - 2016	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Escalade	2004 - 2006	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Escalade (Built after October 2006)	2007 - 2007	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Escalade (Built Before November 2006 )	2007 - 2007	TRW Version 5 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Escalade	2008 - 2009	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Escalade	2010 - 2012	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Escalade	2013 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Escalade	2016 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Escalade	2018 - 2020	-in Gen6 Faraday GM TFA 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Escalade	2021 - 2023	Schrader Gen6 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Lyriq	2023 - 2023	Schrader Gen6 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Seville	2001 - 2004	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
SRX	2004 - 2006	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
SRX	2007 - 2007	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
SRX	2008 - 2009	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
SRX	2010 - 2011	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
SRX	2012 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
SRX	2016 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
STS	2005 - 2008	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	

**Cadillac**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
STS (Clamp-In)	2009 - 2009	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
STS (Snap-In)	2009 - 2011	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
XLR	2004 - 2009	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
XT4 (315Mhz)	2019 - 2023	Schrader Snap-in Faraday 433MHz GM Basic TFA 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
XT5	2017 - 2017	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
XT5	2017 - 2017	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
XT5 (433Mhz)	2018 - 2023	Schrader Snap-in Faraday 433MHz GM Basic TFA 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
XT6	2020 - 2023	Schrader Snap-in Faraday 433MHz GM Basic TFA 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
XTS	2013 - 2014	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
XTS	2015 - 2016	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
XTS	2017 - 2019	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210

**Chevrolet**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Avalanche	2004 - 2004	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Avalanche	2005 - 2006	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Avalanche (Snap-In)	2007 - 2007	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Avalanche (Clamp-In)	2007 - 2007	TRW Version 5 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Avalanche	2008 - 2013	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Aveo	2007 - 2011	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Aveo	2018 - 2018	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Blazer	2019 - 2023	Schrader Snap-in Faraday 433MHz GM Basic TFA 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*

**Chevrolet**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Bolt EV	2017 - 2018	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Bolt EV	2019 - 2021	-in Gen6 Faraday GM TFA 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Bolt EV	2022 - 2023	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Camaro	2010 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Camaro (Snap-In)	2016 - 2022	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Camaro (Snap-In)	2016 - 2022	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Camaro (Clamp-In)	2016 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Camaro Sport	2012 - 2015	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Camaro Sport	2016 - 2018	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Caprice	2011 - 2013	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Caprice	2014 - 2017	Schrader Gen Gamma Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Captiva Sport	2008 - 2017	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
City Express	2015 - 2018	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Cobalt (Snap-In)	2008 - 2010	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Cobalt (Clamp-In)	2008 - 2010	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Colorado	2006 - 2012	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Colorado	2015 - 2017	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Colorado	2018 - 2020	-in Gen6 Faraday GM TFA 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Colorado	2021 - 2023	Schrader Faraday Snap-In 315 MHz			6-210
Corvette	1997 - 2000	Schrader Gen J Clamp-In 315 MHz		6-122*	
Corvette	2001 - 2004	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Corvette	2005 - 2009	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	

## Chevrolet

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Corvette	2010 - 2013	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Corvette	2014 - 2019	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Corvette	2020 - 2029	Schrader Gen6 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Cruze	2011 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Cruze (433Mhz)	2016 - 2018	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Cruze (433Mhz)	2016 - 2018	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Cruze (315Mhz)	2019 - 2020	-in Gen6 Faraday GM TFA 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Equinox	2007 - 2009	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Equinox	2010 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Equinox	2016 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Equinox	2018 - 2020	-in Gen6 Faraday GM TFA 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Equinox	2022 - 2023	Schrader Faraday Snap-In 315 MHz			6-210
Express Series	2007 - 2008	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Express Series	2009 - 2011	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Express Series	2012 - 2023	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
G Series	2008 - 2008	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
HHR (Clamp-In)	2008 - 2009	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
HHR (Snap-In)	2008 - 2010	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
HHR	2011 - 2011	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Impala (Snap-In)	2006 - 2007	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Impala (Clamp-In)	2006 - 2007	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	

## Chevrolet

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Impala	2008 - 2010	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Impala	2011 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Impala (315Mhz)	2016 - 2020	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Malibu (Clamp-In)	2008 - 2012	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Malibu (Snap-In)	2008 - 2012	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Malibu	2013 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Malibu (315Mhz)	2016 - 2019	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Malibu (433Mhz)	2016 - 2019	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Malibu (433Mhz)	2016 - 2019	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Malibu	2020 - 2023	Schrader Snap-in Faraday 433MHz GM Basic TFA 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Monte Carlo (Snap-In)	2006 - 2007	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Monte Carlo (Clamp-In)	2006 - 2007	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Orlando	2012 - 2014	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Silverado	2004 - 2004	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Silverado	2005 - 2006	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Silverado (Clamp-In)	2007 - 2007	TRW Version 5 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Silverado (Snap-In)	2007 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Silverado	2016 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Silverado	2018 - 2019	-in Gen6 Faraday GM TFA 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Silverado (1500)	2020 - 2023	0 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210

## Chevrolet

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Silverado (DRW and SRW)	2020 - 2023	0 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Silverado	2020 - 2021	Schrader Snap-in Faraday 433MHz GM Basic TFA 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Silverado (LTD and HD)	2022 - 2023	Schrader Snap-in Faraday 433MHz GM Basic TFA 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Silverado	2022 - 2023	Schrader Gen6 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Sonic	2012 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Sonic	2016 - 2020	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Spark	2012 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Spark	2016 - 2023	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
SS	2014 - 2014	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
SS	2015 - 2017	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
SSR	2006 - 2007	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Suburban	2004 - 2004	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Suburban	2005 - 2006	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Suburban (Clamp-In)	2007 - 2007	TRW Version 5 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Suburban (Snap-In)	2007 - 2007	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Suburban	2008 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Suburban	2016 - 2020	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Suburban	2021 - 2023	Schrader Gen6 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Tahoe	2004 - 2004	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Tahoe	2005 - 2006	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	

**Chevrolet**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Tahoe (Clamp-In)	2007 - 2007	TRW Version 5 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Tahoe (Snap-In)	2007 - 2007	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Tahoe	2008 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Tahoe	2016 - 2020	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Tahoe	2021 - 2023	Schrader Gen6 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
TrailBlazer	2002 - 2009	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
TrailBlazer (433Mhz)	2021 - 2023	Schrader Snap-in Faraday 433MHz GM Basic TFA 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Traverse	2009 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Traverse (315Mhz)	2016 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Traverse (433Mhz)	2018 - 2023	Schrader Snap-in Faraday 433MHz GM Basic TFA 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Trax	2013 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Trax	2016 - 2022	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Uplander	2008 - 2009	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Volt	2011 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Volt (315Mhz)	2016 - 2016	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Volt (433Mhz)	2017 - 2018	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Volt (433Mhz)	2017 - 2018	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Volt	2019 - 2020	Schrader Faraday Snap-In 315 MHz			6-210

**Chrysler**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
200	2011 - 2014	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
200	2015 - 2016	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208

## Chrysler

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
200	2017 - 2019	TG1D Snap-In with Screw 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
300	2005 - 2007	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
300	2008 - 2008	VDO TG1B Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
300	2009 - 2015	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
300	2016 - 2021	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
300	2022 - 2023	Huf Clamp-In OE 433 MHz		6-109	6-240*
300M	2002 - 2004	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Aspen	2007 - 2009	Schrader Gen Alpha Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Concorde	2002 - 2004	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Crossfire	2004 - 2008	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Intrepid	2002 - 2004	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Pacifica (433Mhz)	2004 - 2004	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Pacifica (315Mhz)	2004 - 2005	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Pacifica	2006 - 2008	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Pacifica	2017 - 2023	TG1D Snap-In with Screw 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
Prowler	1997 - 2001	Schrader Gen 2/3 Clamp-In 315 MHz		6-101*	
Prowler	2002 - 2002	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
PT Cruiser	2007 - 2010	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Sebring (315Mhz)	2007 - 2010	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Sebring (433Mhz)	2008 - 2009	VDO TG1B Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Town and Country	2002 - 2003	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Town and Country	2004 - 2005	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201

### Chrysler

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Town and Country	2006 - 2007	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Town and Country	2008 - 2010	VDO TG1B Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Town and Country	2011 - 2016	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Voyager	2002 - 2003	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Voyager	2020 - 2023	TG1D Snap-In with Screw 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*

### Dodge

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Avenger	2007 - 2014	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
C/V	2012 - 2014	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
C/V	2015 - 2016	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Caliber	2007 - 2010	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Caliber	2011 - 2014	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Caravan	2002 - 2003	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Caravan	2004 - 2005	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Caravan	2006 - 2007	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Challenger (Snap-In)	2010 - 2016	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Challenger (Clamp-In)	2008 - 2021	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Challenger (Snap-In)	2017 - 2021	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Challenger	2022 - 2023	Huf Clamp-In OE 433 MHz		6-109	6-240*
Charger	2006 - 2007	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Charger	2008 - 2008	VDO TG1B Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Charger (Clamp-In)	2009 - 2015	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*

## Dodge

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Charger (Snap-In)	2009 - 2021	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Charger	2022 - 2023	Huf Clamp-In OE 433 MHz		6-109	6-240*
Dakota	2008 - 2010	Schrader Gen Alpha Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Dakota	2011 - 2011	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Dart	2012 - 2018	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
Durango	2006 - 2008	Schrader Gen Alpha Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Durango	2009 - 2009	Schrader Gen Alpha Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Durango	2011 - 2015	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Durango (Snap-In )	2016 - 2017	TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
Durango (Screw-in )	2016 - 2023	TG1D Snap-In with Screw 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
Durango (SRT)	2018 - 2023	TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Grand Caravan	2001 - 2003	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Grand Caravan	2004 - 2007	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Grand Caravan	2008 - 2010	VDO TG1B Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Grand Caravan	2011 - 2020	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Intrepid	2002 - 2004	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Journey	2009 - 2010	VDO TG1B Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Journey	2011 - 2020	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Magnum	2005 - 2007	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Magnum	2008 - 2008	VDO TG1B Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Nitro	2007 - 2010	Schrader Gen Alpha Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*

**Dodge**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Nitro	2011 - 2011	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
ProMaster	2014 - 2016	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Ram Series	2009 - 2009	Schrader Gen Alpha Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Ram Series	2010 - 2013	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Ram Series	2014 - 2016	TRW Version 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-211
Sprinter	2007 - 2010	VDO MB Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B*
Stratus	2007 - 2007	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Viper	2003 - 2010	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Viper	2013 - 2018	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*

**Ferrari**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
296	2022 - 2023	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
550 Maranello Evol.	2002 - 2006	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
575 M-Maranello	2002 - 2006	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
599 GTB/GTO	2004 - 2011	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
612 Scaglietti	2004 - 2011	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
812 Superfast	2019 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
California	2009 - 2016	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Dino	2020 - 2021	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Enzo	2003 - 2004	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
F12 Berlinetta	2012 - 2017	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

**Ferrari**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
F430	2004 - 2007	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
F430	2008 - 2013	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
F458	2010 - 2016	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
F488	2015 - 2020	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
F8 Tributo	2020 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
FF	2011 - 2017	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
XX	2005 - 2007	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
GTC4Lusso T	2017 - 2021	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
LaFerrari	2014 - 2018	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Portofino	2019 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

**Fiat**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
124 Spider	2017 - 2017	VDO TG1C Clamp-In 433 MHz		6-139B*	6-231*
124 Spider	2018 - 2020	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
500	2012 - 2015	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
500	2016 - 2019	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
500E	2016 - 2016	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
500L	2014 - 2015	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
500L	2016 - 2021	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
500X	2014 - 2023	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208

**Ford**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Bronco	2020 - 2023	Schrader Gen 4 Snap-In PAL 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*

**Ford**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
C-Max	2013 - 2019	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Crown Victoria	2006 - 2011	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
EcoSport	2018 - 2022	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437AL*
Edge	2007 - 2010	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Edge	2011 - 2014	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Edge	2015 - 2023	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437AL*
Escape	2005 - 2008	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Escape	2009 - 2019	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Escape	2020 - 2022	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437-1*
E-Series (Band sensor)	2007 - 2010	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
E-Series	2010 - 2016	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
E-Series	2017 - 2020	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
E-Series (SRW)	2021 - 2023	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437-1*
E-Series (DRW)	2021 - 2023	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Expedition	2003 - 2004	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Expedition	2005 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Expedition	2007 - 2010	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Expedition	2011 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Expedition (Limited edition)	2018 - 2018	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437-1*
Expedition	2018 - 2022	Schrader Gen 4 Snap-In PAL 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*

## Ford

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Explorer	2002 - 2005	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Explorer	2006 - 2010	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Explorer	2011 - 2015	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Explorer	2016 - 2023	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437AL*
Fiesta	2011 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Fiesta	2018 - 2020	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437AL*
Five Hundred	2006 - 2007	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Flex	2009 - 2010	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Flex	2011 - 2020	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Focus	2007 - 2009	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Focus	2010 - 2020	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Focus RS	2016 - 2018	Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Freestar	2004 - 2005	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Freestar	2006 - 2007	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
F-Series	2006 - 2008	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
F-Series	2009 - 2014	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
F-Series	2015 - 2022	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437AL*
F-Series Super Duty (Built Before July 2010)	2006 - 2010	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
F-Series Super Duty (Built After June 2010)	2010 - 2016	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
F-Series Super Duty (Single Rear Wheels)	2017 - 2022	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437-1*

**Ford**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Fusion	2006 - 2009	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Fusion	2010 - 2016	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Fusion	2017 - 2021	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437-1*
GT	2017 - 2022	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Mach E	2021 - 2023	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437-1*
Maverick	2022 - 2023	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437AL*
Mustang	2007 - 2009	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Mustang	2010 - 2014	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Mustang	2015 - 2023	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437AL*
Mustang ((Shelby) for Gulf Cooperative Countries (GCC))	2017 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Ranger	2006 - 2011	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Ranger	2019 - 2022	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437AL*
Shelby GT500	2015 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Taurus (Built before June 2010)	2007 - 2010	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Taurus (Built After May 2010)	2010 - 2013	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Taurus	2014 - 2021	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Transit	2010 - 2018	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Transit (315 MHz)	2019 - 2022	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437-1*
Transit (433 MHz)	2021 - 2022	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437-1*
Transit Connect	2010 - 2018	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*

**Ford**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Transit Connect	2019 - 2020	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437AL*
Transit Connect	2021 - 2022	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437-1*

**Freightliner**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Sprinter	2007 - 2013	VDO MB Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B*
Sprinter	2014 - 2021	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Sprinter	2014 - 2021	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*

**Genesis**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
G70	2018 - 2023	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
G80 (433Mhz)	2017 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
G90 (433Mhz)	2017 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
GV70	2022 - 2025	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
GV80	2021 - 2023	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*

**GMC**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Acadia	2007 - 2008	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Acadia	2009 - 2010	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Acadia	2011 - 2012	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Acadia	2013 - 2014	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Acadia	2015 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Acadia (315Mhz)	2016 - 2016	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Acadia (433Mhz)	2017 - 2017	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Acadia (433Mhz)	2017 - 2017	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*

## GMC

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Acadia	2018 - 2023	Schrader Snap-in Faraday 433MHz GM Basic TFA 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Canyon	2007 - 2012	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Canyon	2013 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Canyon	2016 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Canyon	2018 - 2019	-in Gen6 Faraday GM TFA 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Canyon	2020 - 2023	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Envoy	2005 - 2009	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Hummer	2022 - 2022	Schrader Gen6 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Savana	2008 - 2009	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Savana	2010 - 2023	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Sierra	2004 - 2004	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Sierra (Schrader Clamp-In)	2005 - 2007	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Sierra (Schrader Snap-In)	2007 - 2007	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Sierra (TRW Clamp-In)	2007 - 2007	TRW Version 5 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Sierra	2008 - 2009	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Sierra	2010 - 2010	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Sierra	2011 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Sierra	2016 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Sierra	2018 - 2019	-in Gen6 Faraday GM TFA 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Sierra (1500)	2020 - 2023	0 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Sierra (LTD and HD)	2022 - 2023	Schrader Snap-in Faraday 433MHz GM Basic TFA 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*

### GMC

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Sierra	2022 - 2023	Schrader Gen6 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Terrain	2010 - 2015	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Terrain	2016 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Terrain	2018 - 2023	-in Gen6 Faraday GM TFA 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Yukon	2004 - 2004	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Yukon	2005 - 2006	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Yukon (Built after October 2006; Clamp in)	2007 - 2007	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Yukon (Built before November 2006; Clamp in)	2007 - 2007	TRW Version 5 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Yukon	2008 - 2009	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Yukon	2010 - 2010	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Yukon	2011 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Yukon	2016 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Yukon	2018 - 2020	-in Gen6 Faraday GM TFA 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Yukon	2020 - 2023	Schrader Gen6 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*

### Honda

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Accord	2008 - 2012	Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Civic	2008 - 2013	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Crosstour	2010 - 2015	VDO TG1C Clamp-In 315 MHz		6-138	6-231*
CR-V (Steel Wheels)	2007 - 2011	Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
CR-V (Alloy Wheels)	2007 - 2011	Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
CR-V	2012 - 2013	VDO TG1C Clamp-In 315 MHz		6-138	6-231*
CR-Z	2011 - 2013	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	

**Honda**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
CR-Z	2014 - 2015	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Element	2006 - 2008	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Element	2009 - 2011	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
FCX Clarity Fit	2007 - 2014 2008 - 2008	Pacific Clamp-In 315 MHz Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T* 6-116T*	
Fit	2009 - 2012	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Fit	2013 - 2014	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Insight	2010 - 2013	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Insight	2014 - 2014	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Odyssey	2005 - 2007	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Odyssey	2008 - 2010	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Odyssey	2011 - 2013	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Odyssey	2014 - 2017	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Odyssey	2018 - 2020	VDO TG1C Clamp-In 433 MHz		6-140	6-231*
Odyssey	2021 - 2023	Continental New Style TG1C Snap-In 433 MHz			6-505
Odyssey Touring	2005 - 2007	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Odyssey Touring	2008 - 2010	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Odyssey Touring	2011 - 2013	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Odyssey Touring	2014 - 2016	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Passport	2019 - 2022	VDO TG1C Clamp-In 433 MHz		6-140	6-231*
Pilot (Steel Wheels)	2005 - 2005	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Pilot (Alloy Wheels)	2005 - 2008	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Pilot (Alloy Wheels)	2009 - 2015	Pacific Clamp-In 315 MHz		6-116T*	
Pilot (Steel Wheels)	2009 - 2015	Pacific Clamp-In 315 MHz		6-116T*	
Pilot	2016 - 2018	VDO TG1C Clamp-In 433 MHz		6-139B*	6-231*
Pilot	2019 - 2023	VDO TG1C Clamp-In 433 MHz		6-140	6-231*

### Honda

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Ridgeline (Alloy Wheels)	2006 - 2008	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Ridgeline (Steel Wheels)	2006 - 2008	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Ridgeline	2009 - 2014	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Ridgeline	2017 - 2020	VDO TG1C Clamp-In 433 MHz		6-140	6-231*
Ridgeline	2021 - 2023	Continental New Style TG1C Snap-In 433 MHz			6-505
S2000 (Alloy Wheels)	2008 - 2009	Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	

### Hummer

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
H2	2007 - 2009	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
H3	2006 - 2010	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
H3T	2009 - 2010	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	

### Hyundai

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Accent (Lowline)	2006 - 2007	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Accent (Highline)	2006 - 2007	TRW Version 3 Variable Angle Clamp-In 315 MHz		6-109	6-240
Accent (Highline)	2008 - 2011	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Accent	2012 - 2013	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Accent	2014 - 2014	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Accent	2015 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Azera	2006 - 2011	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Azera	2012 - 2013	TRW Version 2 Screw-In Valve Clamp-In 433 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Azera	2014 - 2017	TRW Version 2 Screw-In Valve Clamp-In 433 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Elantra	2007 - 2010	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Elantra	2011 - 2013	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Elantra	2014 - 2016	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236

## Hyundai

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Elantra	2017 - 2020	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Elantra	2021 - 2023	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Elantra N	2022 - 2022	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Elantra GT	2013 - 2014	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Elantra GT	2015 - 2017	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Elantra GT	2018 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Elantra Touring	2009 - 2013	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Entourage	2007 - 2010	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Equus (Lowline)	2011 - 2013	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Equus	2014 - 2014	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Equus	2015 - 2016	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Genesis (Highline)	2009 - 2014	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Genesis	2010 - 2012	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Genesis	2013 - 2016	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Genesis (Sedan)	2015 - 2016	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Ioniq	2016 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Kona	2018 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Nexo	2019 - 2023	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Palisade	2020 - 2022	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Santa Fe (Highline)	2006 - 2008	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*

## Hyundai

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Santa Fe (Lowline)	2008 - 2009	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Santa Fe (Lowline)	2010 - 2012	Lear Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-240
Santa Fe	2013 - 2014	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Santa Fe (XL for 2019)	2015 - 2019	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Santa Fe (Non XL)	2019 - 2023	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Sonata (Lowline)	2006 - 2008	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Sonata (Highline)	2006 - 2008	TRW Version 3 Variable Angle Clamp-In 315 MHz		6-109	6-240
Sonata (Lowline)	2009 - 2010	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Sonata	2011 - 2013	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Sonata	2014 - 2014	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Sonata	2015 - 2019	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Sonata (Non-Hybrid)	2015 - 2016	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Sonata	2020 - 2023	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Tiburon (Lowline)	2007 - 2008	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Tiburon (Highline)	2007 - 2008	TRW Version 3 Variable Angle Clamp-In 315 MHz		6-109	6-240
Tucson (Lowline and built before November 2010)	2006 - 2010	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Tucson (Highline and built before November 2010)	2006 - 2010	TRW Version 3 Variable Angle Clamp-In 315 MHz		6-109	6-240
Tucson (Built After October 2010)	2010 - 2013	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Tucson (Lowline)	2014 - 2015	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Tucson	2016 - 2021	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Tucson	2022 - 2023	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Veloster	2011 - 2019	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*

**Hyundai**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Veloster	2019 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Venue	2020 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Veracruz (Highline)	2006 - 2008	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Veracruz (Lowline)	2008 - 2012	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*

**Infiniti**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
EX (Built before April 2010)	2008 - 2010	LFC1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
EX (Built after March 2010)	2010 - 2014	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
FX (Built Before August 2007)	2003 - 2007	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
FX (Built After July 2007)	2007 - 2008	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
FX (Built Before April 2010)	2009 - 2010	LFC1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
FX (Built After March 2010)	2010 - 2014	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
G	2003 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
G (Sedan)	2007 - 2007	LFC1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
G (Coupe)	2007 - 2007	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
G (Built before April 2010)	2008 - 2010	LFC1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
G (Built After March 2010)	2010 - 2013	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
JX35	2013 - 2014	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
M	2003 - 2007	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
M (Built After August 2007)	2008 - 2008	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
M (Built After July 2007)	2009 - 2010	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	

## Infiniti

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
M	2011 - 2013	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Q40	2015 - 2016	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Q45 (Built Before September 2006)	2003 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Q45 (Built After August 2006)	2006 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Q50	2014 - 2015	VDO TG1C Clamp-In 315 MHz		6-139B*	6-231*
Q50	2016 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Q60	2014 - 2015	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Q60	2017 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Q70	2014 - 2020	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
QX30	2017 - 2020	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
QX4 / SUV	2003 - 2003	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
QX50	2013 - 2018	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
QX50	2019 - 2022	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
QX55	2022 - 2023	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
QX56 (Steel Wheels)	2004 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
QX56 (Alloy Wheels)	2005 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
QX56 (Built Before May 2007)	2007 - 2007	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
QX56 (Built After April 2007)	2007 - 2010	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
QX56	2011 - 2013	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
QX60	2014 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
QX70	2014 - 2019	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	

**Infiniti**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
QX80	2014 - 2017	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
QX80	2017 - 2019	Pacific CCN32 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
QX80 (315Mhz)	2018 - 2022	Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	

**SUZU**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Ascender	2006 - 2008	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
i-290	2007 - 2011	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
i-370	2007 - 2011	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Rodeo	2004 - 2004	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	

**Jaguar**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
E-Pace	2018 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
F-Pace	2017 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
F-Type (433Mhz)	2014 - 2014	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
F-Type (315Mhz)	2014 - 2016	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
F-Type	2015 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
I-Pace	2018 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
S-Type	2005 - 2008	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
S-Type	2005 - 2008	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
S-Type (315Mhz)	2007 - 2008	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Super V8 (433Mhz)	2005 - 2006	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Super V8 (433Mhz)	2005 - 2006	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Super V8 (315Mhz)	2005 - 2006	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201

## Jaguar

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Super V8 (433Mhz)	2007 - 2009	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Super V8 (433Mhz)	2007 - 2009	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Super V8 (315Mhz)	2007 - 2009	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Vanden Plas (433Mhz)	2004 - 2006	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Vanden Plas (433Mhz)	2004 - 2006	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Vanden Plas (315Mhz)	2004 - 2006	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Vanden Plas (433Mhz)	2007 - 2009	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Vanden Plas (433Mhz)	2007 - 2009	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Vanden Plas (315Mhz)	2007 - 2009	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
XE	2016 - 2021	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
XF (433Mhz)	2009 - 2016	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
XF (433Mhz)	2009 - 2016	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
XF (315Mhz)	2009 - 2018	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
XF (433Mhz)	2017 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
XFR (433Mhz)	2010 - 2015	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
XFR (433Mhz)	2010 - 2015	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
XFR (315Mhz)	2010 - 2015	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
XFR-S (433Mhz)	2013 - 2015	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
XFR-S (433Mhz)	2013 - 2015	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
XFR-S (315Mhz)	2013 - 2015	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201

## Jaguar

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
XJ (433Mhz)	2005 - 2009	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
XJ (433Mhz)	2005 - 2009	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
XJ (315Mhz)	2005 - 2009	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
XJ (433Mhz)	2010 - 2011	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
XJ (433Mhz)	2010 - 2011	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
XJ (315Mhz)	2010 - 2011	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
XJ (315Mhz)	2012 - 2021	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
XJ (433Mhz)	2015 - 2021	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
XK (433Mhz)	2005 - 2009	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
XK (433Mhz)	2005 - 2009	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
XK (315Mhz)	2005 - 2009	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
XK (433Mhz)	2010 - 2012	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
XK (433Mhz)	2010 - 2012	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
XK (315Mhz)	2010 - 2010	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
XK (315Mhz)	2011 - 2012	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
XK (315Mhz)	2013 - 2015	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
XK (433Mhz)	2013 - 2015	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
XK (433Mhz)	2013 - 2015	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
X-Type (433Mhz)	2007 - 2009	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
X-Type (433Mhz)	2007 - 2009	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*

**Jaguar**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
X-Type (315Mhz)	2007 - 2009	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201

**Jeep**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Cherokee	2014 - 2023	TRW Version 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-211
Commander	2006 - 2006	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Commander	2007 - 2007	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Commander	2008 - 2009	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Commander	2008 - 2009	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Commander	2008 - 2009	VDO TG1B Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Commander	2008 - 2009	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Commander	2010 - 2010	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Commander	2010 - 2010	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Commander	2010 - 2010	VDO TG1B Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Commander	2010 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Compass	2007 - 2013	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Compass	2014 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Compass	2018 - 2023	TG1D Snap-In with Screw 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
Gladiator (Before July 2021)	2020 - 2021	Schrader Gen 6 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Gladiator (After June 2021)	2021 - 2023	Continental Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
Grand Cherokee	2001 - 2004	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Grand Cherokee	2005 - 2007	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201

## Jeep

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Grand Cherokee	2008 - 2008	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Grand Cherokee	2008 - 2008	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Grand Cherokee	2008 - 2008	VDO TG1B Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Grand Cherokee	2008 - 2008	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Grand Cherokee	2009 - 2010	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Grand Cherokee	2009 - 2010	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Grand Cherokee	2009 - 2010	VDO TG1B Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Grand Cherokee	2009 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Grand Cherokee (Snap-In)	2011 - 2014	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Grand Cherokee (Clamp-In)	2012 - 2015	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Grand Cherokee	2015 - 2015	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Grand Cherokee (Screw in )	2016 - 2022	TG1D Snap-In with Screw 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
Grand Cherokee (Clamp-In)	2016 - 2022	TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Grand Cherokee (Snap-In)	2016 - 2017	TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
Grand Cherokee	2021 - 2027	Continental Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
Grand Wagoneer	2022 - 2023	Continental Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
Liberty	2002 - 2004	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Liberty (433Mhz)	2009 - 2009	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Liberty (433Mhz)	2009 - 2009	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Liberty (433Mhz)	2009 - 2009	VDO TG1B Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201

### Jeep

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Liberty (433Mhz)	2009 - 2009	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Liberty (315Mhz)	2009 - 2010	Schrader Gen Alpha Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Liberty	2011 - 2012	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Patriot	2007 - 2013	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Patriot	2014 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Patriot	2018 - 2018	TG1D Snap-In with Screw 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
Renegade	2015 - 2017	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
Renegade	2018 - 2022	TG1D Snap-In with Screw 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
Wagoneer	2022 - 2023	Continental Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
Wrangler (433Mhz)	2009 - 2009	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Wrangler (433Mhz)	2009 - 2009	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Wrangler (433Mhz)	2009 - 2009	VDO TG1B Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Wrangler (433Mhz)	2009 - 2009	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Wrangler (315Mhz)	2009 - 2010	Schrader Gen Alpha Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Wrangler	2011 - 2012	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Wrangler	2013 - 2014	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Wrangler (Built Before July 2021)	2015 - 2021	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Wrangler (Built After June 2021)	2021 - 2028	Continental Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*

### Kia

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Amanti (Lowline)	2007 - 2009	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240

## Kia

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Amanti (Highline)	2007 - 2009	TRW Version 3 Variable Angle Clamp-In 315 MHz		6-109	6-240
Amanti	2010 - 2011	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Borrego (Lowline)	2009 - 2011	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Cadenza	2014 - 2016	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Cadenza (433Mhz- Limited Edition)	2017 - 2021	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Carnival	2022 - 2023	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Forte	2010 - 2013	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Forte	2014 - 2018	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Forte	2019 - 2022	-in Fixed Angle ver 1 433MHz 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
K5	2021 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
K900	2015 - 2017	Schrader Gen 4 Snap-In 433 MHz			6-207*
K900	2018 - 2021	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Magentis	2008 - 2010	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Niro	2017 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Optima	2006 - 2022	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Optima	2011 - 2012	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Optima (315Mhz)	2013 - 2016	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Optima (433Mhz)	2016 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Rio (Lowline)	2007 - 2011	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Rio	2012 - 2017	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Rio (433Mhz)	2018 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Rondo	2007 - 2012	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*

## Kia

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Sedona	2006 - 2008	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Sedona	2009 - 2014	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Sedona	2015 - 2021	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Seltos	2021 - 2023	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Sorento (Lowline)	2007 - 2010	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Sorento (Highline)	2007 - 2010	TRW Version 3 Variable Angle Clamp-In 315 MHz		6-109	6-240
Sorento	2011 - 2013	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Sorento	2014 - 2015	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Sorento	2016 - 2017	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Sorento	2018 - 2020	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Sorento	2021 - 2023	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Soul	2010 - 2013	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Soul	2014 - 2022	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Spectra (Lowline)	2006 - 2009	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Sportage (Lowline)	2005 - 2008	TRW Version 3 Variable Angle Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240
Sportage (Highline)	2005 - 2008	TRW Version 3 Variable Angle Clamp-In 315 MHz		6-109	6-240
Sportage (Lowline)	2009 - 2013	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Sportage (Lowline)	2014 - 2016	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Sportage	2016 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Stinger	2018 - 2023	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Telluride	2020 - 2023	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210

### Lamborghini

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Aventador	2012 - 2022	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Gallardo	2008 - 2014	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Huracan	2014 - 2022	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Murcielago	2006 - 2013	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
One Off	2016 - 2018	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Reventon	2007 - 2008	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Urus	2018 - 2021	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

### Land Rover

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Defender	2015 - 2015	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Defender	2020 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Discovery	2017 - 2023	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Discovery Sport	2015 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
LR2 (433Mhz)	2008 - 2013	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
LR2 (433Mhz)	2008 - 2013	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
LR2 (315Mhz)	2008 - 2015	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
LR2 (433Mhz)	2015 - 2015	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
LR3	2002 - 2005	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
LR3 (433Mhz)	2006 - 2009	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
LR3 (433Mhz)	2006 - 2009	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
LR3 (315Mhz)	2006 - 2009	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201

## Land Rover

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
LR4 (433Mhz)	2010 - 2011	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
LR4 (433Mhz)	2010 - 2011	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
LR4 (315Mhz)	2010 - 2011	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
LR4 (315Mhz)	2012 - 2014	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
LR4 (433Mhz)	2015 - 2016	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Range Rover	2002 - 2005	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Range Rover (433Mhz)	2006 - 2011	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Range Rover (433Mhz)	2006 - 2011	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Range Rover (315Mhz)	2006 - 2011	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Range Rover	2012 - 2013	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Range Rover	2014 - 2014	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Range Rover	2015 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Range Rover Evoque	2011 - 2014	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Range Rover Evoque (315Mhz)	2015 - 2015	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Range Rover Evoque (433Mhz)	2015 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Range Rover Sport (433Mhz)	2006 - 2011	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Range Rover Sport (433Mhz)	2006 - 2011	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Range Rover Sport (315Mhz)	2006 - 2011	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Range Rover Sport	2012 - 2013	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Range Rover Sport (433Mhz)	2014 - 2014	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*

**Land Rover**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Range Rover Sport (315Mhz)	2014 - 2014	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Range Rover Sport (315Mhz)	2015 - 2015	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Range Rover Sport (433Mhz)	2015 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Range Rover Velar	2018 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*

**Lexus**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
CT	2011 - 2017	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
ES	2007 - 2012	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
ES (Lowline)	2013 - 2018	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
ES (Highline)	2013 - 2018	LFB1 OE replacement sensor 315 MHz		6-116T*	
ES	2018 - 2023	Pacific Clamp-In 315 MHz		6-116T*	6-507
GS	2005 - 2012	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
GS (Lowline)	2013 - 2021	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
GS (Highline)	2013 - 2021	LFB1 OE replacement sensor 315 MHz		6-116T*	
GX (Built Before March 2006)	2004 - 2006	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
GX (Built after February 2006 and before September 2017)	2006 - 2017	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
GX (Built after August 2017)	2017 - 2019	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
GX	2020 - 2022	Pacific Clamp-In 315 MHz		6-116T*	6-507
HS	2010 - 2012	Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
IS	2006 - 2013	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
IS (IS F Only)	2014 - 2014	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
IS (Lowline)	2014 - 2020	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
IS (Highline)	2014 - 2020	LFB1 OE replacement sensor 315 MHz		6-116T*	
IS	2021 - 2023	Pacific Clamp-In 315 MHz		6-116T*	6-507
LC (433Mhz)	2017 - 2018	Pacific CCT3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
LC (315Mhz)	2018 - 2022	Pacific Clamp-In 315 MHz		6-116T*	6-507
LFA	2012 - 2016	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	

## Lexus

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
LS	2007 - 2012	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
LS	2013 - 2017	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
LS (Lowline)	2018 - 2022	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
LS (Highline)	2018 - 2022	Pacific Clamp-In 315 MHz		6-116T*	6-507
LX	2005 - 2016	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
LX	2016 - 2023	Pacific Clamp-In 315 MHz		6-116T*	6-507
NX (Lowline)	2015 - 2021	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
NX (Highline)	2015 - 2021	LFB1 OE replacement sensor 315 MHz		6-116T*	
NX	2022 - 2023	Pacific Clamp-In 315 MHz		6-116T*	6-507
RC (Lowline)	2015 - 2020	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
RC (Highline)	2015 - 2020	LFB1 OE replacement sensor 315 MHz		6-116T*	
RC	2021 - 2023	Pacific Clamp-In 315 MHz		6-116T*	6-507
RX (Made in USA)	2006 - 2015	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
RX (Made in Japan)	2006 - 2015	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
RX	2016 - 2022	Pacific Clamp-In 315 MHz		6-116T*	6-507
SC	2002 - 2006	Pacific Clamp-In - Blue 315 MHz		6-116T*	
SC	2007 - 2010	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
UX	2019 - 2022	Pacific Clamp-In 315 MHz		6-116T*	6-507

## Lincoln

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Aviator	2003 - 2005	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Aviator	2020 - 2022	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437-1*
Continental (433Mhz)	2017 - 2020	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Continental (315Mhz)	2017 - 2020	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437AL*
Corsair	2020 - 2022	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437-1*
Mark LT	2007 - 2008	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
MKC	2015 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
MKC	2018 - 2020	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437-1*

**Lincoln**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
MKS	2009 - 2010	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
MKS	2011 - 2019	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
MKT	2010 - 2010	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
MKT	2011 - 2015	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
MKT (315Mhz)	2016 - 2020	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
MKX	2007 - 2010	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
MKX	2011 - 2015	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
MKX (433Mhz)	2016 - 2018	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
MKX (315Mhz)	2016 - 2021	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437AL*
MKZ	2007 - 2009	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
MKZ	2010 - 2016	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
MKZ (433Mhz)	2017 - 2017	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
MKZ (315Mhz)	2017 - 2021	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437AL*
Nautilus (Limited edition)	2019 - 2023	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437-1*
Navigator	2003 - 2004	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Navigator	2005 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Navigator	2007 - 2010	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Navigator	2011 - 2017	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Navigator (315Mhz)	2018 - 2022	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-437AL*
Town Car	2006 - 2011	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		

### Lincoln

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Zephyr	2006 - 2006	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		

### Lotus

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Elise	2008 - 2011	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
Evora	2010 - 2015	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
Exige	2008 - 2014	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	

### Maserati

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Coupe	2002 - 2007	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Ghibli	2014 - 2022	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Gran Cabrio	2010 - 2013	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Gran Sport	2005 - 2006	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Gran Turismo	2008 - 2012	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Gran Turismo	2013 - 2013	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Gran Turismo	2014 - 2021	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Levante	2017 - 2022	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Quattroporte	2004 - 2009	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Quattroporte	2010 - 2012	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Quattroporte	2013 - 2013	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Quattroporte	2014 - 2022	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Spyder	2002 - 2005	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

## Mazda

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
2	2011 - 2013	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
2	2014 - 2015	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
3	2004 - 2013	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
3	2019 - 2022	Continental TG1D Screw-in Valve Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
5	2006 - 2015	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
6	2005 - 2013	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
6	2019 - 2020	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
B Series	2007 - 2011	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
CX-3	2019 - 2022	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
CX-30	2020 - 2022	Continental TG1D Screw-in Valve Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
CX-5	2017 - 2022	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
CX-7	2007 - 2012	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
CX-9	2007 - 2013	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
CX-9	2014 - 2014	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
CX-9	2015 - 2015	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
CX-9	2018 - 2019	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
CX-9	2020 - 2022	Continental TG1D Screw-in Valve Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
MX-5	2006 - 2013	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
MX-5 (With Run Flats)	2009 - 2014	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
MX-5	2011 - 2020	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*

**Mazda**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
MX-5	2021 - 2022	Continental TG1D Screw-in Valve Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
MX-30 (CA Only)	2022 - 2022	Continental TG1D Screw-in Valve Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
RX-8	2004 - 2011	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Tribute	2006 - 2008	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Tribute	2009 - 2011	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		

**McLaren**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
570	2016 - 2021	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
600LT	2019 - 2021	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
650S	2014 - 2016	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
675LT	2016 - 2016	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
720S	2017 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
MP4-12C	2012 - 2014	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
P1	2013 - 2015	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

**Mercedes**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
A-Class	2019 - 2022	Huf Gen 2 Slim Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-240*
AMG GT ((190))	2016 - 2021	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
AMG GT (4 Door (290))	2019 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
B-Class	2014 - 2018	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
B-Class	2019 - 2021	Huf Gen 2 Slim Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-240*
C-Class	2008 - 2009	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
C-Class	2010 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*

## Mercedes

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
C-Class	2010 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
C-Class	2011 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
C-Class	2011 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
C-Class (Built Before December 2013)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
C-Class (Built Before December 2013)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
C-Class (Built After December 2013)	2014 - 2021	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
C-Class	2022 - 2022	Schrader Gen 6 WAL Gen Delta Clamp-in 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
CLA-Class (Built Before February 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
CLA-Class (Built Before February 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
CLA-Class (Built After January 2014)	2014 - 2022	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
CL-Class (433Mhz)	2000 - 2006	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
CL-Class (315Mhz)	2001 - 2007	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
CL-Class (315Mhz)	2007 - 2010	VDO MB Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B*
CL-Class (433Mhz)	2007 - 2009	VDO MB Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B
CL-Class (433Mhz)	2010 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
CL-Class (433Mhz)	2010 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
CL-Class (433Mhz)	2011 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
CL-Class (433Mhz)	2011 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
CL-Class (433Mhz)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
CL-Class (433Mhz)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*

## Mercedes

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
CLK-Class	2006 - 2009	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
CLK-Class	2006 - 2009	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
CLS-Class	2005 - 2005	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
CLS-Class (433Mhz)	2006 - 2009	VDO MB Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B
CLS-Class (315Mhz)	2006 - 2011	VDO MB Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B*
CLS-Class	2012 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
CLS-Class	2012 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
CLS-Class (Built Before February 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
CLS-Class (Built Before February 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
CLS-Class (Built After January 2014)	2014 - 2015	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
CLS-Class (433Mhz)	2016 - 2018	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
CLS-Class (433Mhz)	2016 - 2018	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
CLS-Class	2019 - 2023	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
E-Class	2000 - 2005	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
E-Class (433Mhz)	2006 - 2009	VDO MB Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B
E-Class (315Mhz)	2006 - 2009	VDO MB Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B*
E-Class	2010 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
E-Class	2010 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
E-Class (433Mhz)	2011 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
E-Class (433Mhz)	2011 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*

## Mercedes

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
E-Class (Built Before February 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
E-Class (Built Before February 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
E-Class (Built After January 2014)	2014 - 2017	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
E-Class	2018 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
EQC	2021 - 2023	Schrader Gen 6 WAL Gen Delta Clamp-in 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
EQS	2022 - 2023	Schrader Gen 6 ? 433 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
G-Class	2007 - 2007	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
G-Class	2007 - 2007	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
G-Class (Built Before February 2015)	2008 - 2015	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
G-Class (Built Before February 2015)	2008 - 2015	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
G-Class (Built After January 2015)	2015 - 2018	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
G-Class	2019 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
GLA-Class	2015 - 2020	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
GLA-Class	2021 - 2023	Huf Gen 2 Slim Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-240*
GLB-Class	2020 - 2022	Huf Gen 2 Slim Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-240*
GLC-Class	2016 - 2022	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
GL-Class (433Mhz)	2007 - 2009	VDO MB Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B
GL-Class	2010 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
GL-Class	2010 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
GL-Class (433Mhz)	2011 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
GL-Class (433Mhz)	2011 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*

## Mercedes

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
GL-Class (Built Before April 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
GL-Class (Built Before April 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
GL-Class (Built After March 2014)	2014 - 2020	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
GLE-Class	2016 - 2018	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
GLE-Class	2019 - 2022	Huf Gen 2 Slim Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-240*
GLK-Class	2010 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
GLK-Class	2010 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
GLK-Class (433Mhz)	2011 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
GLK-Class (433Mhz)	2011 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
GLK-Class (Built Before January 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
GLK-Class (Built Before January 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
GLK-Class (Built After December 2013)	2014 - 2017	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
GLS-Class	2017 - 2019	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
GLS-Class	2020 - 2022	Huf Gen 2 Slim Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-240*
Maybach S600	2016 - 2018	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
M-Class (433Mhz)	2006 - 2008	VDO MB Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B
M-Class (315Mhz)	2006 - 2009	VDO MB Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B*
M-Class (433Mhz)	2009 - 2009	VDO MB Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B
M-Class	2010 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
M-Class	2010 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*

## Mercedes

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
M-Class	2011 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
M-Class	2011 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
M-Class	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
M-Class	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
M-Class	2015 - 2015	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Metris	2016 - 2022	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
R-Class (433Mhz)	2006 - 2009	VDO MB Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B
R-Class (315Mhz)	2006 - 2009	VDO MB Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B*
R-Class (433Mhz)	2009 - 2009	VDO MB Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B
R-Class	2010 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
R-Class	2010 - 2010	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
R-Class (433Mhz)	2011 - 2012	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
R-Class (433Mhz)	2011 - 2012	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
S-Class (433Mhz)	2000 - 2006	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
S-Class (315Mhz)	2000 - 2006	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
S-Class (433Mhz)	2007 - 2009	VDO MB Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B
S-Class (315Mhz)	2007 - 2010	VDO MB Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B*
S-Class	2010 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
S-Class	2010 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
S-Class (Built Before February 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*

## Mercedes

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
S-Class (Built Before February 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
S-Class (Built After January 2014)	2014 - 2022	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
S-Class	2020 - 2022	Schrader Gen 6 WAL Gen Delta Clamp-in 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
S-Class (Sedan)	2021 - 2022	Schrader Gen 6 ? 433 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
SLC-Class	2017 - 2020	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
SL-Class (433Mhz)	2000 - 2005	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
SL-Class (315Mhz)	2000 - 2005	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
SL-Class (433Mhz)	2006 - 2012	VDO MB Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B
SL-Class (315Mhz)	2006 - 2012	VDO MB Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B*
SL-Class (433Mhz)	2013 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
SL-Class (433Mhz)	2013 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
SL-Class (Built Before January 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
SL-Class (Built Before January 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
SL-Class (Built After December 2013)	2014 - 2020	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
SLK-Class	2008 - 2011	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
SLK-Class	2008 - 2011	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
SLK-Class	2012 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
SLK-Class	2012 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
SLK-Class (Built Before January 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
SLK-Class (Built Before January 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
SLK-Class (Built After December 2013)	2014 - 2019	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235

### Mercedes

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
SLR-Class (315Mhz)	2001 - 2005	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
SLR-Class (433Mhz)	2001 - 2007	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
SLR-Class	2006 - 2007	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
SLR-Class (433Mhz)	2008 - 2009	VDO MB Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B
SLR-Class (315Mhz)	2008 - 2009	VDO MB Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B*
SLS-Class	2011 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
SLS-Class	2011 - 2013	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
SLS-Class (Built Before February 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
SLS-Class (Built Before February 2014)	2014 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
SLS-Class (Built After January 2014)	2014 - 2015	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Sprinter	2007 - 2014	VDO MB Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-206B*
Sprinter (433Mhz)	2010 - 2013	VDO MB Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-218
Sprinter (433Mhz)	2014 - 2018	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Sprinter (433Mhz)	2014 - 2018	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Sprinter	2019 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235

### Mercury

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Grand Marquis	2006 - 2011	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Mariner	2006 - 2008	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Mariner	2009 - 2011	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Milan	2007 - 2009	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		

**Mercury**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Milan	2010 - 2011	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Montego	2006 - 2007	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Monterey	2006 - 2007	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Mountaineer	2002 - 2005	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Mountaineer	2006 - 2010	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Sable	2008 - 2009	Lear Banded Ford 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		

**Mini**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Cabrio	2007 - 2009	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Cabrio (Built Before April 2014)	2010 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Cabrio (Built After March 2014)	2014 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Clubman (Built Before October 2009)	2007 - 2009	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Clubman (Built After September 2009 and Built Before August 2014)	2009 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Clubman (Built After July 2014)	2014 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Cooper	2007 - 2009	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Cooper (R56)	2010 - 2015	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Cooper (F55)	2015 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Countryman (Built Before April 2014)	2010 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Countryman (Built After March 2014)	2014 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Coupe (Built Before April 2014)	2012 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Coupe (Built After March 2014)	2014 - 2015	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

**Mini**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Paceman (Built Before April 2014)	2013 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Paceman (Built After March 2014)	2014 - 2016	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Roadster (Built Before April 2014)	2012 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Roadster (Built After March 2014)	2014 - 2015	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

**Mitsubishi**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Eclipse (Alloy Wheels)	2006 - 2009	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Eclipse (Steel Wheels)	2006 - 2007	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Eclipse	2010 - 2012	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Eclipse Cross	2018 - 2023	VDO TG1D Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
Endeavor	2004 - 2006	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Endeavor	2006 - 2009	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Endeavor	2010 - 2011	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Galant	2004 - 2006	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-104	
Galant (Alloy Wheels)	2007 - 2009	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Galant (Steel Wheels)	2007 - 2012	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Galant	2010 - 2012	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
i-MiEV	2012 - 2012	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
i-MiEV	2013 - 2018	VDO TG1D Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
Lancer	2008 - 2017	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Mirage (Snap-In)	2014 - 2020	VDO TG1D Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208

**Mitsubishi**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Mirage (Clamp-In)	2014 - 2023	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Montero	2003 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Outlander	2006 - 2007	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Outlander	2008 - 2021	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Outlander Sport	2013 - 2013	VDO TG1D Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
Outlander Sport	2014 - 2021	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Raider	2008 - 2009	Schrader Gen Alpha Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
RVR	2011 - 2017	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
RVR	2018 - 2021	VDO TG1D Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208

**Nissan**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
350Z	2003 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
350Z	2007 - 2009	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
370Z	2009 - 2009	LFC1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
370Z (Built Before July 2010)	2010 - 2010	LFC1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
370Z (Built After June 2010)	2010 - 2021	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Altima (315Mhz)	2007 - 2013	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Altima	2012 - 2012	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Altima (433Mhz)	2013 - 2014	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Altima	2015 - 2018	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Altima	2019 - 2023	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208

## Nissan

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Ariya	2022 - 2022	VDO TG1D Evo Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
Armada (Alloy Wheels, SE)	2004 - 2008	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Armada	2005 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Armada (LE)	2008 - 2013	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Armada	2014 - 2016	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Armada (Built After May 2017/433Mhz)	2017 - 2018	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Armada (Built Before June 2017)	2017 - 2017	Pacific CCN32 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Armada (315Mhz)	2018 - 2022	Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Cube	2009 - 2012	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Cube (Krom, SL)	2011 - 2013	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Cube	2013 - 2014	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Cube Ikey	2011 - 2014	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Frontier	2003 - 2004	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Frontier (Alloy Wheels)	2005 - 2008	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Frontier (Steel Wheels)	2005 - 2008	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Frontier	2009 - 2013	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Frontier	2014 - 2015	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Frontier (315Mhz)	2016 - 2021	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Frontier (433Mhz)	2020 - 2021	VDO Screw-In Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-505
Frontier	2022 - 2023	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208

## Nissan

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
GT-R	2009 - 2013	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
GT-R	2014 - 2014	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
GT-R	2015 - 2016	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
GT-R	2017 - 2022	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Juke	2011 - 2011	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Juke (With I-Key; Built between 07/11-09/11)	2012 - 2012	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Juke (With I-Key)	2012 - 2015	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Juke (Without I-Key)	2012 - 2015	LFC1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Juke	2016 - 2020	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Juke Ikey	2011 - 2020	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Kicks	2018 - 2022	Pacific Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Leaf	2011 - 2013	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Leaf (Built after December 2012)	2013 - 2014	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Leaf	2015 - 2016	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Leaf	2017 - 2017	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Leaf	2018 - 2022	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
Maxima (Built Before May 2006)	2006 - 2007	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Maxima (Built After April 2006)	2007 - 2010	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Maxima (Built before May 2012)	2011 - 2012	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Maxima (Built after April 2012)	2012 - 2015	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*

## Nissan

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Maxima	2016 - 2018	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Maxima	2019 - 2022	VDO Screw-In Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-505
Micra	2017 - 2021	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
Murano	2003 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Murano	2007 - 2009	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Murano	2010 - 2012	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Murano (Built after November 2011)	2011 - 2014	LFC1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Murano	2015 - 2018	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Murano	2019 - 2022	VDO Screw-In Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-505
NV Series (1500;2500;3500)	2012 - 2021	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
NV-200	2013 - 2021	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Pathfinder	2003 - 2003	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Pathfinder	2004 - 2004	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Pathfinder (Built Before April 2004)	2004 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Pathfinder	2007 - 2010	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Pathfinder (Schrader Clamp-In)	2011 - 2012	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Pathfinder (Continental)	2012 - 2012	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Pathfinder	2013 - 2021	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Pathfinder	2022 - 2023	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
Qashqai	2017 - 2021	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208

## Nissan

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Quest (Steel Wheels)	2004 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Quest (Built before January 2007)	2005 - 2007	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Quest (Built after December 2006)	2007 - 2009	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Quest	2011 - 2016	Pacific Clamp-In replacement 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Quest	2017 - 2017	Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Rogue (Built before July 2012)	2008 - 2012	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Rogue (Built before June 2012)	2012 - 2013	LFC1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Rogue	2014 - 2016	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
Rogue	2017 - 2021	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
Rogue	2022 - 2023	VDO TG1D Evo Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-504*
Rogue Select	2014 - 2015	LFC1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Rogue Sport	2017 - 2022	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
Sentra (Alloy Wheels)	2007 - 2008	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Sentra (Steel Wheels)	2007 - 2010	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Sentra	2011 - 2012	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Sentra (Without I-Key)	2013 - 2016	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Sentra (With I-Key)	2013 - 2016	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Sentra (With I-Key)	2017 - 2019	VDO TG1D Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
Sentra (Without I-Key)	2017 - 2022	VDO TG1D Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-208
Sentra (315Mhz)	2020 - 2022	Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	

## Nissan

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Titan (Steel Wheels)	2004 - 2005	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Titan (Alloy Wheels)	2004 - 2007	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Titan	2007 - 2011	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Titan (Alloy Wheels)	2011 - 2015	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Titan (Steel Wheels)	2014 - 2015	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Titan	2016 - 2016	LFC1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Titan	2017 - 2022	Pacific CCN32 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Versa	2007 - 2011	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Versa (SL)	2012 - 2019	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Versa	2012 - 2012	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Versa	2013 - 2019	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Versa	2020 - 2022	Pacific Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		
Versa Note (SL)	2014 - 2021	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Versa Note	2014 - 2021	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Xterra	2003 - 2004	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Xterra (Alloy Wheels)	2005 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Xterra (Steel Wheels)	2006 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Xterra (Built Before November 2013)	2007 - 2013	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-101*	
Xterra (Built after October 2013)	2013 - 2015	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*

### Plymouth

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Prowler	2002 - 2002	Schrader Gen 2/3 Clamp-In 315 MHz		6-101*	

### Pontiac

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
G3	2008 - 2010	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
G5	2008 - 2008	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
G5	2009 - 2010	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
G6	2008 - 2008	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
G6	2009 - 2010	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
G8	2008 - 2009	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Grand Prix	2007 - 2008	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Montana-SV6	2008 - 2009	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	
Solstice	2008 - 2010	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Torrent	2007 - 2009	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Vibe (Made in Japan)	2008 - 2010	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Vibe (Made in USA)	2008 - 2010	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Wave	2007 - 2009	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*

### Porsche

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
718 Boxster	2017 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
911	2005 - 2007	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
911	2008 - 2009	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
911	2010 - 2011	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
911 (315Mhz)	2012 - 2015	Huf Gen 2 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

**Porsche**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
911 (433Mhz)	2012 - 2016	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
911 (433Mhz)	2017 - 2023	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
911 (315Mhz)	2018 - 2022	Huf Gen 3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
997 GT3	2007 - 2009	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
997 GT3	2010 - 2011	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Boxster	2005 - 2007	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Boxster	2008 - 2009	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Boxster	2010 - 2012	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Boxster (315Mhz)	2013 - 2015	Huf Gen 2 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Boxster (433Mhz)	2013 - 2016	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Boxster (433Mhz)	2017 - 2023	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Boxster (315Mhz)	2018 - 2020	Huf Gen 3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Carerra GT	2004 - 2005	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Cayenne (433Mhz)	2002 - 2006	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Cayenne (315Mhz)	2003 - 2006	Huf Gen 1 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Cayenne (433Mhz)	2008 - 2009	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Cayenne (315Mhz)	2008 - 2009	Huf Gen 2 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Cayenne	2010 - 2010	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Cayenne	2011 - 2014	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Cayenne (433Mhz)	2015 - 2023	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

### Porsche

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Cayenne (315Mhz)	2017 - 2022	Huf Gen 3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Cayman	2005 - 2008	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Cayman	2009 - 2013	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Cayman (433Mhz)	2014 - 2015	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Cayman (315Mhz)	2014 - 2016	Huf Gen 2 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Cayman (433Mhz)	2017 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Cayman (315Mhz)	2018 - 2022	Huf Gen 3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Macan (433Mhz)	2015 - 2023	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Macan (315Mhz)	2018 - 2022	Huf Gen 3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Panamera (433Mhz)	2010 - 2013	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Panamera (315Mhz)	2010 - 2013	Huf Gen 2 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Panamera (433Mhz)	2014 - 2023	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Panamera (315Mhz)	2018 - 2022	Huf Gen 3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Taycan (315Mhz)	2020 - 2022	-in Separate valve G3.4 433MHz VW/Porsche 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Taycan (433Mhz)	2020 - 2023	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

### RAM

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
1500	2019 - 2023	Schrader Gen 6 PAL Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
2500/3500	2019 - 2023	TRW Version 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-211
3500 Dually (Steel wheel outer sensor)	2014 - 2018	TRW Version 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-211
3500 Dually (Alloy wheel outer sensor)	2014 - 2021	TRW Truck TPMS Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		

**RAM**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
3500 Dually (2 rear inner wheels)	2014 - 2023	TRW Version 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-211
3500 Dually (Steel wheel outer sensor)	2019 - 2023	TRW Version 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-211
ProMaster	2014 - 2023	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
ProMaster City	2015 - 2023	Schrader Gen Gamma Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235
Truck (315Mhz)	2008 - 2009	Schrader Gen Alpha Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Truck (433Mhz)	2009 - 2009	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Truck (433Mhz)	2009 - 2009	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Truck (433Mhz)	2009 - 2009	VDO TG1B Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Truck (433Mhz)	2009 - 2009	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Truck	2010 - 2013	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Truck	2014 - 2023	TRW Version 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-211

**Rolls Royce**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Cullinan	2020 - 2022	Huf Gen 2 Slim Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-240*
Dawn	2016 - 2021	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Drophead Coupe	2009 - 2011	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Ghost	2009 - 2015	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Ghost	2016 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Phantom	2007 - 2011	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Phantom	2012 - 2016	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Phantom	2017 - 2022	Schrader Gen Delta Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-235

## Rolls Royce

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Wraith	2014 - 2021	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Wraith	2016 - 2016	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

## Saab

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
9-3	2004 - 2007	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
9-3	2008 - 2012	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
9-4X	2011 - 2011	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
9-5	2004 - 2007	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
9-5	2008 - 2009	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
9-5	2010 - 2012	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
9-7X	2005 - 2009	Schrader Gen J Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-102*	

## Saturn

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Astra	2008 - 2009	Schrader Gen 2/3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
Aura	2007 - 2008	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Aura	2009 - 2010	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Outlook (Clamp-In)	2007 - 2008	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Outlook (Snap-In)	2008 - 2010	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Sky	2008 - 2010	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201
Vue	2007 - 2010	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*

## Scion

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
FR-S	2013 - 2016	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
iM	2016 - 2014	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	

**Scion**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
iQ	2012 - 2015	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
tC (Built before June 2006)	2006 - 2016	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
xB	2008 - 2016	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
xD	2008 - 2016	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	

**Smart**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Fortwo	2008 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Fortwo	2008 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Fortwo	2015 - 2021	Schrader High Speed Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Fortwo	2015 - 2021	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210

**Subaru**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Ascent	2019 - 2022	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
B9 Tribeca	2006 - 2007	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-119	
BRZ	2013 - 2021	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Crosstrek	2015 - 2016	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Crosstrek	2018 - 2022	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Forester	2008 - 2014	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Forester	2015 - 2017	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Forester	2018 - 2022	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Impreza	2008 - 2014	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Impreza	2015 - 2016	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Impreza	2017 - 2022	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210

**Subaru**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Legacy (Clamp-In)	2004 - 2008	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-119	
Legacy (Snap-In)	2008 - 2009	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Legacy	2010 - 2014	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Legacy	2015 - 2017	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Legacy	2018 - 2022	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Outback	2004 - 2007	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-119	
Outback	2008 - 2014	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Outback	2015 - 2017	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Outback	2018 - 2022	Schrader Faraday Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-210
Tribeca	2008 - 2014	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
WRX	2009 - 2014	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
WRX	2015 - 2019	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
WRX STI	2009 - 2015	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
WRX STI	2016 - 2019	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
XV Crosstrek	2013 - 2016	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
XV Crosstrek	2017 - 2017	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*

**Suzuki**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Equator	2009 - 2013	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
Forenza	2007 - 2008	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Grand Vitara	2005 - 2013	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	

**Suzuki**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Kizashi	2010 - 2013	VDO TG1C Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
Reno	2007 - 2008	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
SX4	2007 - 2013	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
Verona	2005 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
XL-7	2005 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
XL-7	2007 - 2011	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-108*	6-201

**Tesla**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Model 3 (Built Before October 2020)	2017 - 2020	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Model 3 (Built After September 2020)	2020 - 2023	Sysgration Tesla Bluetooth BLE			6-284-BS*
Model S (Built Before June 2021)	2014 - 2021	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Model S (Built After May 2021)	2021 - 2023	Sysgration Tesla Bluetooth BLE			6-284-BS*
Model X (Built Before October 2021)	2014 - 2021	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Model X (Built After September 2021)	2021 - 2029	Sysgration Tesla Bluetooth BLE			6-284-BS*
Model Y (Built After September 2020)	2020 - 2030	Sysgration Tesla Bluetooth BLE			6-284-BS*
Roadster (HUF (VIN 001-500))	2008 - 2010	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*

**Toyota**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
4 Runner	2003 - 2017	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
4 Runner	2018 - 2019	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
4 Runner	2020 - 2023	Pacific Clamp-In 315 MHz		6-116T*	
Avalon	2006 - 2012	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	6-507
Avalon (Lowline)	2013 - 2022	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Avalon (Highline)	2016 - 2022	Pacific Clamp-In 315 MHz		6-116T*	6-507
Camry (Made in Japan)	2006 - 2011	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Camry (Made in USA)	2006 - 2011	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	

## Toyota

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Camry (Highline)	2012 - 2022	Pacific Clamp-In 315 MHz		6-116T*	
Camry (Lowline)	2012 - 2022	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	6-507
CH-R (433Mhz)	2017 - 2019	Pacific CCT3 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
CH-R (315Mhz)	2018 - 2022	Pacific Clamp-In 315 MHz		6-116T*	
Corolla (Made in Japan)	2007 - 2013	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	6-507
Corolla (Made in USA)	2007 - 2013	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Corolla (Lowline)	2014 - 2019	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Corolla (Steel Wheels)	2019 - 2022	Pacific Clamp-In 315 MHz		6-116T*	6-507
Corolla (Alloy Wheels)	2020 - 2023	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
FJ Cruiser	2007 - 2014	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
GR86	2022 - 2023	Pacific Clamp-In 315 MHz		6-116T*	6-507
GT86	2017 - 2021	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Highlander (Made in Japan)	2007 - 2013	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Highlander (Made in USA)	2007 - 2013	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Highlander (With Smart-Key)	2014 - 2019	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Highlander (Without Smart-Key (made in Canada))	2014 - 2019	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Highlander	2020 - 2022	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Land Cruiser	2005 - 2007	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Land Cruiser	2008 - 2015	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Land Cruiser	2016 - 2021	Pacific Clamp-In 315 MHz		6-116T*	6-507
Matrix (Made in USA)	2007 - 2011	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Matrix (Made in Japan)	2007 - 2011	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Matrix	2012 - 2014	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Mirai	2016 - 2023	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	

## Toyota

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Prius	2006 - 2012	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Prius	2013 - 2015	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Prius	2016 - 2020	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Prius	2020 - 2021	Pacific Clamp-In 315 MHz		6-116T*	
Prius	2022 - 2022	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	6-507
Prius C	2012 - 2019	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Prius V	2012 - 2016	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Prius V	2017 - 2019	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
RAV4 (Made in Japan)	2006 - 2012	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
RAV4 (Made in Canada)	2009 - 2013	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
RAV4 (Made in Canada (W/O Smart-Key))	2013 - 2018	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
RAV4 (Made in Japan)	2013 - 2013	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
RAV4 (Made in Canada (With Smart-Key))	2014 - 2018	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
RAV4	2019 - 2022	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
RAV4 (Made in Canada (W/O Smart-Key))	2019 - 2022	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Sequoia (Steel Wheels)	2004 - 2007	Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Sequoia (Alloy Wheels)	2004 - 2007	Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Sequoia (Alloy Wheels)	2008 - 2013	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Sequoia (Steel Wheels)	2008 - 2013	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Sequoia	2014 - 2017	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Sequoia (TRW)	2018 - 2020	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236
Sequoia (Pacific)	2020 - 2021	Pacific Clamp-In 315 MHz		6-116T*	6-507

## Toyota

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Sequoia	2022 - 2022	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Sienna (Alloy Wheels)	2006 - 2013	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Sienna (Steel Wheels)	2006 - 2013	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Sienna	2014 - 2020	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Sienna	2021 - 2022	TRW Version 4 Clamp-In 315 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-211
Solara	2006 - 2008	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Supra (Built After April 2019 )	2019 - 2026	Huf Gen 2 Slim Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-240*
Tacoma (Alloy Wheels)	2005 - 2006	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Tacoma (Steel Wheels)	2005 - 2006	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Tacoma (Alloy Wheels)	2007 - 2015	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Tacoma (Steel Wheels)	2007 - 2015	Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Tacoma (Alloy Wheels)	2016 - 2021	Pacific Clamp-In 315 MHz		6-116T*	6-507
Tacoma (Steel Wheels)	2016 - 2023	LFC1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Tundra (Alloy Wheels)	2005 - 2006	Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Tundra (Steel Wheels)	2005 - 2006	Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Tundra (Alloy Wheels)	2007 - 2011	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Tundra (Steel Wheels)	2007 - 2011	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Tundra (Alloy Wheels)	2012 - 2015	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Tundra (Steel Wheels)	2012 - 2017	TRW Version 1 Fixed Valve Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-114*	
Tundra	2017 - 2017	Pacific Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Tundra (Steel Wheels)	2018 - 2022	TRW Clamp-In 315 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Tundra (Alloy Wheels)	2018 - 2022	TRW Version 2 Screw-In Valve Clamp-In 315 MHz	HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-125*	6-236

**Toyota**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Venza	2009 - 2016	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Venza	2021 - 2022	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Yaris	2007 - 2011	Pacific LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Yaris	2012 - 2012	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	
Yaris	2013 - 2019	LFB1 OE replacement sensor 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-116T*	

**Volkswagen**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Arteon	2019 - 2022	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Beetle	2008 - 2010	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
CC	2009 - 2011	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
CC	2012 - 2013	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
CC	2014 - 2014	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
CC	2015 - 2018	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
EOS	2007 - 2016	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
Golf	2006 - 2011	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
GTI (18" Wheels)	2006 - 2007	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
GTI	2006 - 2012	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
Jetta	2006 - 2010	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
Passat (18" Wheels)	2006 - 2008	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
Passat	2006 - 2010	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
Phaeton (433Mhz)	2003 - 2006	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*

**Volkswagen**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
Phaeton (315Mhz)	2003 - 2006	Huf Gen 1.2 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
R32	2008 - 2008	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
Rabbit	2006 - 2007	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
Rabbit	2008 - 2009	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
Routan	2009 - 2014	Schrader Gen 4 Snap-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
Routan	2009 - 2014	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
Routan	2009 - 2014	VDO TG1B Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
Routan	2009 - 2014	Schrader Gen Alpha Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-146*	6-228T*
Tiguan	2008 - 2011	VDO TG1B Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-115	6-201
Touareg	2004 - 2007	HUF Gen 1.2 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Touareg	2008 - 2009	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Touareg	2010 - 2010	HUF Gen 1 Clamp-In -S037 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-110	6-220B*
Touareg	2011 - 2014	HUF Gen 2.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*
Touareg	2015 - 2021	HUF Gen 3.4 Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-109	6-240*

**Volvo**

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
C30	2007 - 2013	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
C70	2006 - 2013	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
S40 (433Mhz)	2004 - 2007	VDO TG1B Clamp-In -S174 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-141*	6-201
S40 (433Mhz)	2004 - 2007	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
S40	2008 - 2012	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*

## Volvo

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
S60	2004 - 2008	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
S60	2009 - 2009	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
S60	2011 - 2014	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
S60	2015 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
S80	2004 - 2006	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
S80	2007 - 2011	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
S80	2012 - 2014	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
S80	2015 - 2016	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
V50	2005 - 2011	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
V60	2014 - 2014	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
V60	2015 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
V70	2004 - 2007	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
V70	2008 - 2011	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
XC60	2009 - 2010	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
XC60	2010 - 2013	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-140	6-231*
XC60	2014 - 2014	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
XC60	2015 - 2022	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
XC70	2004 - 2007	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
XC70	2008 - 2011	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
XC70	2012 - 2014	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*

### Volvo

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
XC70	2015 - 2016	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-138	6-231*
XC90	2004 - 2004	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*
XC90 (315Mhz)	2005 - 2011	Schrader Gen 2/3 Clamp-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-118*	
XC90 (433Mhz)	2008 - 2008	VDO TG1C Clamp-In 433 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG	6-139B*	6-231*
XC90	2011 - 2022	Schrader Gen 4 Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*

### VPG

Model	Years	OE Sensor	U-Pro	Service Kit	Valve
MV-1	2012 - 2016	Schrader Faraday Snap-In 315 MHz	HTS-A66DG / HTS-A66DD / HTS-A78DD / HTS-A78DG / HTS-A78ED / HTS-A78EG		6-207*

### \*Alternative Parts are Available

Service parts that are marked with an asterisk (\*) have alternatives available, as detailed below.

Primary Part	Alternative Part(s)
6-114	6-127, 6-125, 6-143T
6-139B	6-139, 6-149
6-116T	6-117, 6-111
6-108	6-141, 6-129
6-102	6-113, 6-105, 6-118, 6-122
6-101	6-103
6-122	6-118
6-141	6-129
6-146	6-120, 6-144
6-125	6-114, 6-127, 6-143T
6-118	6-122, 6-112
6-231	6-231C
6-240	6-241, 6-242, 6-243, 6-204, 6-205
6-220B	6-221, 6-222B, 6-223B, 6-204
6-207	6-213, 6-207C, 6-216, 6-203, 6-225
6-504	6-207, 6-213, 6-207C, 6-216, 6-203, 6-225
6-228T	6-228S
6-206B	6-205
6-437AL	6-210
6-437-1	6-207, 6-213, 6-207C, 6-216, 6-203, 6-225
6-284-BS	6-284-BK

## TPMS Sensors

**HTS-A78DD - U-Pro Hybrid 2.5 Universal Sensor w/ Dual Valves**

The Only 1-SKU Solution. \*315 MHz is not permitted in Europe..  
\*\*You must uphold the sensor warranty by servicing the valve every time the tire bead is broken.  
Nut Torque: 44.25in-lbs  
Screw Torque: 12.39in-lbs

**HTS-A78DG - U-Pro Hybrid 2.5 Universal Sensor w/ Snap-In**

The Only 1-SKU Solution. \*315 MHz is not permitted in Europe..  
\*\*You must uphold the sensor warranty by servicing the valve every time the tire bead is broken.  
Nut Torque: Snap-In  
Screw Torque: 12.39in-lbs

**HTS-A78DH - U-Pro Hybrid 2.5 Universal Sensor w/ Silver Clamp-In Valve**

The Only 1-SKU Solution. \*315 MHz is not permitted in Europe..  
\*\*You must uphold the sensor warranty by servicing the valve every time the tire bead is broken.  
Nut Torque: 44.25in-lbs  
Screw Torque: 12.39in-lbs

**HTS-A78DK - U-Pro Hybrid 2.5 Universal Sensor w/ Black Clamp-In Valve**

The Only 1-SKU Solution. \*315 MHz is not permitted in Europe..  
\*\*You must uphold the sensor warranty by servicing the valve every time the tire bead is broken.  
Nut Torque: 44.25in-lbs  
Screw Torque: 12.39in-lbs

**HTS-A78ED - U-Pro Hybrid NFC Universal Sensor w/ Dual Valves**

The 1st Program-by-Phone Sensor. What Sets this Sensor Apart?. The U-Pro Hybrid NFC is the first NFC-enabled universal sensor users can program with their smartphones.\*. This innovative solution is well-suited for tire supply distributors, tire dealers and auto part stores alike. What is NFC?. NFC is a short-range wireless technology that allows compatible devices to communicate. Its most common use on a smartphone is making quick and easy payments with Apple Pay or Google Pay. NFC Benefits & App Features . Increase Productivity Without Compromising on Accuracy. Rapid Programming . The app can program Hybrid NFC sensors in a tap, outperforming diagnostic tools. Two Ways to Program . Create a new ID and use any diagnostic tool to relearn a vehicle. Alternatively, manually enter an existing OE sensor ID and skip the relearn process altogether. . Zero Interference. Users can rest assured they have programmed the correct sensor thanks to NFC's short-range transmission.. Free to Download & Update. Say goodbye to subscription fees and manual updates. The app updates itself, so users do not have to!\*\* As a result, the latest vehicle coverage is always at your fingertips. Additionally, the Hybrid NFC boasts the same features as the [Hybrid 2.5](#). \*Available for NFC-enabled Android phones and all iPhones from the iPhone 7 onwards (with a minimum of iOS 15). . \*\*Mobile data or a Wi-Fi connection is required. Apple users must select 'Remote' from the settings menu.  
Nut Torque: 44.25in-lbs  
Screw Torque: 12.39in-lbs

**HTS-A78EG - U-Pro Hybrid NFC Universal Sensor w/ Snap-In**

The 1st Program-by-Phone Sensor. What Sets this Sensor Apart?. The U-Pro Hybrid NFC is the first NFC-enabled universal sensor users can program with their smartphones.\*. This innovative solution is well-suited for tire supply distributors, tire dealers and auto part stores alike. What is NFC?. NFC is a short-range wireless technology that allows compatible devices to communicate. Its most common use on a smartphone is making quick and easy payments with Apple Pay or Google Pay. NFC Benefits & App Features . Increase Productivity Without Compromising on Accuracy. Rapid Programming . The app can program Hybrid NFC sensors in a tap, outperforming diagnostic tools. Two Ways to Program . Create a new ID and use any diagnostic tool to relearn a vehicle. Alternatively, manually enter an existing OE sensor ID and skip the relearn process altogether. . Zero Interference. Users can rest assured they have programmed the correct sensor thanks to NFC's short-range transmission.. Free to Download & Update. Say goodbye to subscription fees and manual updates. The app updates itself, so users do not have to!\*\* As a result, the latest vehicle coverage is always at your fingertips. Additionally, the Hybrid NFC boasts the same features as the [Hybrid 2.5](#). \*Available for NFC-enabled Android phones and all iPhones from the iPhone 7 onwards (with a minimum of iOS 15). . \*\*Mobile data or a Wi-Fi connection is required. Apple users must select 'Remote' from the settings menu.  
Nut Torque: Snap-In  
Screw Torque: 12.39in-lbs



### HTS-A78EH - U-Pro Hybrid NFC Universal Sensor w/ Silver Clamp-In Valve

The 1st Program-by-Phone Sensor. What Sets this Sensor Apart? The U-Pro Hybrid NFC is the first NFC-enabled universal sensor users can program with their smartphones.\*. This innovative solution is well-suited for tire supply distributors, tire dealers and auto part stores alike. What is NFC? . NFC is a short-range wireless technology that allows compatible devices to communicate. Its most common use on a smartphone is making quick and easy payments with Apple Pay or Google Pay. NFC Benefits & App Features . Increase Productivity Without Compromising on Accuracy. Rapid Programming . The app can program Hybrid NFC sensors in a tap, outperforming diagnostic tools. Two Ways to Program . Create a new ID and use any diagnostic tool to relearn a vehicle. Alternatively, manually enter an existing OE sensor ID and skip the relearn process altogether. . Zero Interference. Users can rest assured they have programmed the correct sensor thanks to NFC's short-range transmission. . Free to Download & Update. Say goodbye to subscription fees and manual updates. The app updates itself, so users do not have to!\*\* As a result, the latest vehicle coverage is always at your fingertips. Additionally, the Hybrid NFC boasts the same features as the [Hybrid 2.5](#). \*Available for NFC-enabled Android phones and all iPhones from the iPhone 7 onwards (with a minimum of iOS 15). . \*\*Mobile data or a Wi-Fi connection is required. Apple users must select 'Remote' from the settings menu.

Nut Torque: 44.25in-lbs  
Screw Torque: 12.39in-lbs



### HTS-A78EK - U-Pro Hybrid NFC Universal Sensor w/ Black Clamp-In Valve

The 1st Program-by-Phone Sensor. What Sets this Sensor Apart? The U-Pro Hybrid NFC is the first NFC-enabled universal sensor users can program with their smartphones.\*. This innovative solution is well-suited for tire supply distributors, tire dealers and auto part stores alike. What is NFC? . NFC is a short-range wireless technology that allows compatible devices to communicate. Its most common use on a smartphone is making quick and easy payments with Apple Pay or Google Pay. NFC Benefits & App Features . Increase Productivity Without Compromising on Accuracy. Rapid Programming . The app can program Hybrid NFC sensors in a tap, outperforming diagnostic tools. Two Ways to Program . Create a new ID and use any diagnostic tool to relearn a vehicle. Alternatively, manually enter an existing OE sensor ID and skip the relearn process altogether. . Zero Interference. Users can rest assured they have programmed the correct sensor thanks to NFC's short-range transmission. . Free to Download & Update. Say goodbye to subscription fees and manual updates. The app updates itself, so users do not have to!\*\* As a result, the latest vehicle coverage is always at your fingertips. Additionally, the Hybrid NFC boasts the same features as the [Hybrid 2.5](#). \*Available for NFC-enabled Android phones and all iPhones from the iPhone 7 onwards (with a minimum of iOS 15). . \*\*Mobile data or a Wi-Fi connection is required. Apple users must select 'Remote' from the settings menu.

Nut Torque: 44.25in-lbs  
Screw Torque: 12.39in-lbs



### HTS-A66DD - Hybrid 2.0 Dual Valve Dual-Frequency Sensor

U-Pro Hybrid 2.0 Sensor. The only single SKU solution. A dual frequency, configurable and programmable TPMS sensor with dual valves... The use of 315Mhz is prohibited in Europe.  
Nut Torque: 35.4in-lbs  
Screw Torque: 12.39in-lbs



### HTS-A66DG - Hybrid 2.0 Snap-In Dual-Frequency Sensor

U-Pro Hybrid 2.0 Sensor. The only dual frequency, configurable and programmable TPMS sensor... The use of 315Mhz is prohibited in Europe.  
Nut Torque: Snap-in  
Screw Torque: 12.39in-lbs



### HTS-A66DH - Hybrid 2.0 Clamp-In Dual-Frequency Sensor

U-Pro Hybrid 2.0 Sensor. The only dual frequency, configurable and programmable TPMS sensor... The use of 315Mhz is prohibited in Europe.  
Nut Torque: 35.4in-lbs  
Screw Torque: 12.39in-lbs



### HTS-A66DK - Hybrid 2.0 Black Clamp-In Dual-Frequency Sensor

U-Pro Hybrid 2.0 Sensor. The only dual frequency, configurable and programmable TPMS sensor... The use of 315Mhz is prohibited in Europe.  
Nut Torque: 35.4in-lbs  
Screw Torque: 12.39in-lbs



### HTS-B10BN-US - U-Pro Hybrid BLE - Black Clamp-In

An aftermarket BLE (Bluetooth Low Energy) TPMS sensor for Tesla vehicles..  
Nut Torque: 44.25in-lbs  
Screw Torque: 12.39in-lbs



### HTS-B10BP-US - U-Pro Hybrid BLE - Graphite Clamp-In

An aftermarket BLE (Bluetooth Low Energy) TPMS sensor for Tesla vehicles..  
Nut Torque: 44.25in-lbs  
Screw Torque: 12.39in-lbs

### TPMS Service Parts

 <p><b>6-101 - Box Of 10 Service Kits for Schrader Gen 2/3</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen 2/3 type sensors. Nut Torque: 37.62in-lbs</p>	 <p><b>6-102 - Box Of 10 Service Kits for Schrader Gen J</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen J type sensors. Nut Torque: 61.96in-lbs</p>
 <p><b>6-103 - Box Of 10 Service Kits for Schrader Gen 2/3</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen 2/3 type sensors. Nut Torque: 37.62in-lbs</p>	 <p><b>6-104 - Box Of 10 Service Kits for Schrader Gen 2/3</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen 2/3 type sensors. Nut Torque: 53.1in-lbs</p>
 <p><b>6-105 - Box Of 10 Service Kits for Schrader Gen J</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen J type sensors. Nut Torque: 37.62in-lbs</p>	 <p><b>6-106 - Box Of 10 Service Kits for Schrader Gen 2/3</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen 2/3 type sensors. Nut Torque: 44.25in-lbs</p>
 <p><b>6-108 - Box Of 10 Service Kits for VDO TG1B</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 black valve cap, 1 gray valve cap and 1 valve core. These service kits are suitable for use with VDO TG1B type sensors. Nut Torque: 70.81in-lbs</p>	 <p><b>6-109 - Box Of 10 Service Kits for HUF Gen 2 Sensor</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These service kits are suitable for use with TRW version 2 type sensors. Nut Torque: 35.4in-lbs</p>
 <p><b>6-110 - Box Of 10 Service Kits for HUF Sensor</b></p> <p>A box of 10 service kits with each including: 1 nut, 1 rubber grommet, 2 metal washers, 1 screw, 1 valve core, 1 anti-rotation pin and 1 valve cap. Used for the Huf Gen 1 ball-joint type TPMS valves for early Huf, TRW and Lear sensors. Please note that this service kit cannot be used on gen2 or higher versions of the valve. Nut Torque: 35.4in-lbs</p>	 <p><b>6-111 - Box Of 10 Service Kits for Pacific LFB1 / LFC1</b></p> <p>A box of 10 service kits with each including: 1 nut, 1 rubber grommet, 1 metal washers, 1 screw, 1 valve core, and 1 valve cap. Used for the Huf Gen 2 type TPMS sensors. Nut Torque: 35.4in-lbs</p>
 <p><b>6-112 - Box Of 10 Service Kits for Schrader Gen 2/3</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 metal valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen 2/3 type sensors. Nut Torque: 48.68in-lbs</p>	 <p><b>6-113 - Box Of 10 Service Kits for Schrader Gen J</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen J type sensors. Nut Torque: 53.1in-lbs</p>
 <p><b>6-114 - Box Of 10 Service Kits for TRW version 1 sensor</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These service kits are suitable for use with TRW version 2 type sensors. Nut Torque: 48.68in-lbs</p>	 <p><b>6-115 - Box Of 10 Service Kits for VDO TG1B</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These service kits are suitable for use with VDO TG1B type sensors. Nut Torque: 70.81in-lbs</p>

 <p><b>6-116T - Box Of 10 Service Kits for Pacific LFB1 / LFC1</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. This service kit is suitable for use with Pacific LFB1/LFC1 type sensors.</p> <p>Nut Torque: 35.4in-lbs</p>	 <p><b>6-117 - Box Of 10 Service Kits for Pacific LFB1 / LFC1</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. This service kit is suitable for use with Pacific LFB1/LFC1 type sensors.</p> <p>Nut Torque: 44.25in-lbs</p>
 <p><b>6-118 - Box Of 10 Service Kits for Schrader Gen 2/3</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen 2/3 type sensors.</p> <p>Nut Torque: 53.1in-lbs</p>	 <p><b>6-119 - Box Of 10 Service Kits for Schrader Gen 2/3</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 metal valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen 2/3 type sensors.</p> <p>Nut Torque: 37.62in-lbs</p>
 <p><b>6-120 - Box Of 10 Service Kits for Schrader Gen Alpha</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen Alpha type sensors.</p> <p>Nut Torque: 57.53in-lbs</p>	 <p><b>6-122 - Box Of 10 Service Kits for Schrader Gen J</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen J type sensors.</p> <p>Nut Torque: 53.1in-lbs</p>
 <p><b>6-123 - Box Of 10 Service Kit for Schrader Gen 1</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 o-ring, 1 metal valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen 1 type sensors.</p> <p>Nut Torque: 53.1in-lbs</p>	 <p><b>6-125 - Box Of 10 Service Kits for TRW Version 2 Sensor</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These service kits are suitable for use with TRW type sensors.</p> <p>Nut Torque: 61.96in-lbs</p>
 <p><b>6-127 - Box Of 10 Service Kits for TRW Version 1 Sensor</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These service kits are suitable for use with TRW version 1 type sensors.</p> <p>Nut Torque: 39.83in-lbs</p>	 <p><b>6-129 - Box Of 10 Service Kits for VDO TG1B</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These service kits are suitable for use with VDO TG1B type sensors.</p> <p>Nut Torque: 70.81in-lbs</p>
 <p><b>6-138 - Box Of 10 Service Kits for VDO TG1C</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. This service kit is suitable for use with VDO TG1C type sensors.</p> <p>Nut Torque: 70.81in-lbs</p>	 <p><b>6-139 - Service Kit for VDO TG1C</b></p> <p>Service kit, including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These service kit are suitable for use with VDO TG1C type sensors.</p> <p>Nut Torque: 70.81in-lbs</p>
 <p><b>6-139B - Box Of 10 Service Kits for VDO TG1C</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. This service kit is suitable for use with VDO TG1C type sensors.</p> <p>Nut Torque: 70.81in-lbs</p>	 <p><b>6-140 - Box Of 10 Service Kits for VDO TG1C</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 metal washer, 1 valve cap and 1 valve core. This service kit is suitable for use with VDO TG1C type sensors.</p> <p>Nut Torque: 53.1in-lbs</p>

 <p><b>6-141 - Box Of 10 Service Kits for VDO TG1B</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These service kits are suitable for use with VDO TG1B type sensors. Nut Torque: 53.1in-lbs</p>	 <p><b>6-142 - Box Of 10 Service Kits for Schrader Gen 2/3</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 4 rings, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen 2/3 type sensors. Nut Torque: 37.62in-lbs</p>
 <p><b>6-143T - Box Of 10 Service Kits for Schrader Gen 2/3</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen 2/3 type sensors. Nut Torque: 37.62in-lbs</p>	 <p><b>6-144 - Box Of 10 Service Kits for Schrader Gen Alpha</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen Alpha type sensors. Nut Torque: 53.1in-lbs</p>
 <p><b>6-145 - Box Of 10 Service Kits for Schrader Gen 2/3</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 4 rings, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen 2/3 type sensors. Nut Torque: 53.1in-lbs</p>	 <p><b>6-146 - Box Of 10 Service Kits for Schrader Gen Alpha</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen Alpha type sensors. Nut Torque: 53.1in-lbs</p>
 <p><b>6-147 - Box Of 10 Service Kits for Schrader Gen 2/3</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These service kits are suitable for use with Schrader Gen 2/3 type sensors. Nut Torque: 53.1in-lbs</p>	 <p><b>6-148 - Box Of 10 Service Kits for VDO TG1B</b></p> <p>A box of service kits, with each including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These service kits are suitable for use with VDO TG1B type sensors. Nut Torque: 53.1in-lbs</p>
 <p><b>6-149 - Box Of 10 Service Kits for VDO TG1C</b></p> <p>A box of service kits, with each including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These service kits are suitable for use with VDO TG1C type sensors. Nut Torque: 53.1in-lbs</p>	 <p><b>6-152F - Box Of 10 Service Kits for U-Pro and OE-R Sensors</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. This service kit is suitable for use with U-Pro and OE-R clamp-in sensors. Nut Torque: 35.4in-lbs</p>
 <p><b>6-153 - Box Of 10 Service Kits for Baolong Sensor</b></p> <p>A box of 10 service kits, with each including: 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. This service kit is suitable for use with type sensors. Nut Torque: 44.25in-lbs</p>	 <p><b>6-157A-SH - Box Of 10 Graphite Service Kits for T-Pro Hybrid 3.5 and OE-R 4200 Clamp-In Sensors</b></p> <p>A box of 10 service kits, with each including: 1 Graphite Nut, 1 Rubber Grommet, 1 Plastic Washer, 1 Valve Cap and 1 Valve Core. This service kit is suitable for use with EU-Pro 3.5 and OE-R 4200 Clamp-In sensors. Nut Torque: 44.25in-lbs Screw Torque: 12.39in-lbs</p>
 <p><b>6-201 - Box Of 10 Replacement Valves for VDO TG1B</b></p> <p>A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These valves are suitable for use with VDO TG1B type sensors. Nut Torque: 53.1in-lbs Screw Torque: 8.85in-lbs</p>	 <p><b>6-203 - Box Of 10 replacement Clamp-In Valves for Schrader REV 4</b></p> <p>A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These valves are suitable for use with Schrader Gen 4 type sensors. Nut Torque: 70.81in-lbs Screw Torque: 12.39in-lbs</p>



### 6-203B - Box Of 10 Replacement Clamp-In Valves for Schrader High Speed Sensor

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These valves are suitable for use with Schrader High Speed type sensors.  
 Nut Torque: 70.81in-lbs  
 Screw Torque: 12.39in-lbs



### 6-204 - Box Of 10 Replacement Clamp-In Gen 1 Valves for HUF-56mm

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 valve cap and 1 valve core. These valves are suitable for use with Huf Gen 1 type sensors. The length of this valve is 56mm.  
 Nut Torque: 35.4in-lbs  
 Screw Torque: 35.4in-lbs



### 6-205 - Box Of 10 Replacement Clamp-In Gen 2 Valves for HUF - 43mm

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 valve cap and 1 valve core. These valves are suitable for use with Huf Gen 2 type sensors. The length of this valve is 43mm.  
 Nut Torque: 35.4in-lbs  
 Screw Torque: N/A



### 6-206B - Box Of 10 Replacement Clamp-In Valves for VDO MB

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 screw, 1 valve cap and 1 valve core. These valves are suitable for use with VDO mb type sensors.  
 Nut Torque: 53.1in-lbs  
 Screw Torque: N/A



### 6-207 - Box Of 10 Replacement Snap-In Valves for Schrader Rev 4

A box of 10 snap-in valves. These valves are self-threading and suitable for use with Schrader gen 4 type sensors.a box of 10 snap-in valves, each include: 1 valve stem, 1 screw and 1 valve cap.  
 Nut Torque: Snap-In  
 Screw Torque: 12.39in-lbs



### 6-207B - Box Of 10 High Speed Dual Fitment Snap-In Valves for Schrader Sensors

A box of 10 snap-in valves, with each including 1 valve stem, 1 screw and 1 valve cap.  
 Nut Torque: Snap-In  
 Screw Torque: 12.39in-lbs



### 6-207C - Box Of 10 Replacement Chrome Snap-In Valves for Schrader Gen 4

A Box of 10 Chrome sleeved snap-in valves. These valve are suitable for use with Schrader Gen 4 type sensors.snap in valve, each include: 1 valve stem, 1 screw and 1 valve cap.  
 Nut Torque: Snap-In  
 Screw Torque: 12.39in-lbs



### 6-208 - Box Of 10 Replacement Snap-In Valves for VDO TG1D

A box of 10 snap-in valves. This service kit is suitable for use with VDO TG1D type sensors.a box of 10 snap-in valves, each include: 1 valve stem, 1 screw and 1 valve cap.  
 Nut Torque: Snap-In  
 Screw Torque: Clip-In



### 6-210 - Box Of 10 Replacement Snap-In Valves for Schrader Snap-In Sensor

A box of 10 snap-in valves. These valves are suitable for use with Schrader Snap-In Sensors. A box of 10 snap-in valves, each include: 1 valve stem, 1 screw and 1 valve cap.  
 Nut Torque: Snap-In  
 Screw Torque: 12.39in-lbs



### 6-211 - Box Of 10 Replacement Snap-In Valves for TRW Version 4 sensor

A box of 10 snap-in valves. These valves are suitable for use with TRW snap-in sensors.a box of 10 snap-in valves, each include: 1 valve stem, 1 screw and 1 valve cap.  
 Nut Torque: Snap-In  
 Screw Torque: 12.39in-lbs



### 6-213 - Box Of 10 High Speed Snap-In Valves for Schrader Rev 4

A box of 10 high speed snap-in valves. These valves are suitable for use with Schrader Gen 4 type sensors.  
 Nut Torque: Snap-In  
 Screw Torque: 12.39in-lbs



### 6-214 - Box Of 10 Replacement Snap-In Valves for ALI Sens.it

A box of 10 snap-in valves. This valve is suitable for use with Alligator sens.it sensors.a box of 10 snap-in valves, each include: 1 valve stem, and 1 valve cap.  
 Nut Torque: Snap-In  
 Screw Torque: N/A

**6-215A - Box Of 10 Replacement Snap-In Valves for CUB**

A box of 10 snap-in valves. This valve is suitable for use with cub multi sensors.a box of 10 snap-in valves, each include: 1 valve stem, 1 screw and 1 valve cap.  
Nut Torque: N/A  
Screw Torque: 12.39in-lbs

**6-216 - Box Of 10 Replacement Clamp-In Valves for Schrader Rev 4**

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These valves are suitable for use with Schrader Gen 4 type sensors.  
Nut Torque: 53.1in-lbs  
Screw Torque: 12.39in-lbs

**6-218 - Box Of 10 Replacement Clamp-In Valves for VDO MB**

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 screw, 1 valve cap and 1 valve core. These valves are suitable for use with VDO mb type sensors.  
Nut Torque: 53.1in-lbs  
Screw Torque: N/A

**6-220B - Box Of 10 Replacement Clamp-In Gen 1 Valves for HUF - 43mm**

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These valves are suitable for use with Huf Gen 1 type sensors. The length of this valve is 43mm.  
Nut Torque: 35.4in-lbs  
Screw Torque: 35.4in-lbs

**6-221 - Box Of 10 Replacement Clamp-In Gen 1 Valves for HUF - 48mm**

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 anti-rotation pin,1 screw , 1 valve cap and 1 valve core.. These valves are suitable for use with Huf Gen 1 type sensors. The length of this valve is 48mm.  
Nut Torque: 35.4in-lbs  
Screw Torque: 35.4in-lbs

**6-222B - Box Of 10 Replacement Clamp-In Gen 1 Valves for HUF - 49mm**

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 anti-rotation pin, 1 screw, 1 valve cap and 1 valve core. These valves are suitable for use with Huf Gen 1 type sensors. The length of this valve is 49mm.  
Nut Torque: 35.4in-lbs  
Screw Torque: 35.4in-lbs

**6-223B - Box Of 10 Replacement Clamp-In Gen 1 Valves for HUF - 51mm**

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 metal washer,1 screw , 1 anti-rotation pin 1 valve cap and 1 valve core. These valves are suitable for use with Huf Gen 1 type sensors. The length of this valve is 51mm.  
Nut Torque: 35.4in-lbs  
Screw Torque: 35.4in-lbs

**6-225 - Box Of 10 replacement Clamp-In Valves for Schrader REV 5**

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 valve cap and 1 valve core. These valves are suitable for use with Schrader rev 5 type sensors.  
Nut Torque: 53.1in-lbs  
Screw Torque: 12.39in-lbs

**6-228S - Box of 10 Replacment Clamp-In valves for Schrader Gen Alpha Sensor**

A box of 10 clamp-in valves, with each including: 1 Valve Stem, 1 Domed Washer, 1 Valve Cap, 1 Collar, 1 Rubber Grommet, and 1 Valve core. These valves are suitable for use with Schrader Gen Alpha type sensors.  
Nut Torque: 53.1in-lbs  
Screw Torque: N/A

**6-228T - Box Of 10 Replacement Clamp-In Valves for Schrader Gen Alpha**

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 domed washer. These valves are suitable for use with Schrader Gen Alpha type sensors.  
Nut Torque: 53.1in-lbs  
Screw Torque: N/A

**6-231 - Box Of 10 Replacement Clamp-In Valves for VDO TG1C**

A box of 10 clamp-in valves, with each including: 1 valve stem and 1 valve cap. These valves are suitable for use with VDO TG1C type sensors.  
Nut Torque: 70.81in-lbs  
Screw Torque: N/A

**6-231C - Replacement Clamp-In Valve for VDO TG1C**

Clamp-in valve, including: 1 valve stem and 1 valve cap. These valve are suitable for use with VDO TG1C type sensors.  
Nut Torque: 70.81in-lbs  
Screw Torque: N/A

**6-233 - Box Of 10 Replacement Black Clamp-In Valves for CUB**

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap , 1 screw and 1 valve core. These valves are suitable for use with cub multi sensors.

Nut Torque: 35.4in-lbs  
Screw Torque: N/A

**6-235 - Box Of 10 Replacement Clamp-In Valves for Schrader Gen Gamma**

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These valves are suitable for use with Schrader Gen Gamma and Schrader Gen Delta type sensors.

Nut Torque: 53.1in-lbs  
Screw Torque: N/A

**6-236 - Box Of 10 Replacement Clamp-In Valves for TRW Version 2**

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 valve cap and 1 valve core. These valves are suitable for use with TRW type sensors.

Nut Torque: 35.4in-lbs  
Screw Torque: N/A

**6-237-GBK - Box of 10 Black Clamp-In Valves for Cub Sensor**

Nut Torque: ?Nm  
Screw Torque: ?Nm

**6-240 - Box Of 10 Replacement Clamp-In Gen 2 Valves for HUF - 43mm**

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These valves are suitable for use with Huf Gen 2 type sensors. The length of this valve is 43mm.

Nut Torque: 35.4in-lbs  
Screw Torque: 35.4in-lbs

**6-241 - Box Of 10 Replacement Clamp-In Gen 2 Valves for HUF - 48mm**

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These valves are suitable for use with Huf Gen 2 type sensors. The length of this valve is 48mm.

Nut Torque: 35.4in-lbs  
Screw Torque: 35.4in-lbs

**6-242 - Box Of 10 Replacement Clamp-In Gen 2 Valves for HUF - 49mm**

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These valves are suitable for use with Huf Gen 2 type sensors. The length of this valve is 49mm.

Nut Torque: 35.4in-lbs  
Screw Torque: 35.4in-lbs

**6-243 - Box Of 10 Replacement Clamp-In Gen 2 Valves for HUF - 51mm**

A box of 10 clamp-in valves, with each including: 1 valve stem, 1 nut, 1 rubber grommet, 1 plastic washer, 1 valve cap and 1 valve core. These valves are suitable for use with Huf Gen 2 type sensors. The length of this valve is 51mm.

Nut Torque: 35.4in-lbs  
Screw Torque: 35.4in-lbs

**6-266 - Box Of 10 Clamp-In Valves for U-Pro Hybrid 2.0**

A box of 10 clamp-in valves, with each including 1 valve stem, 1 screw and 1 valve cap.  
Nut Torque: 35.4in-lbs  
Screw Torque: 12.39in-lbs

**6-266-SH - Box Of 10 Graphite Clamp-In Valves for U-Pro Hybrid 2.0**

A box of 10 clamp-in valves, with each including 1 valve stem, 1 screw and 1 valve cap.  
Nut Torque: 44.25in-lbs  
Screw Torque: 12.39in-lbs

**6-266A-SH - Box of 10 Graphite Clamp-In Valves for U-Pro Hybrid 2.0**

A box of 10 Graphite clamp-in valves, with each including 1 valve stem, 1 screw and 1 valve cap.  
Nut Torque: 44.25in-lbs  
Screw Torque: 12.39in-lbs

**6-266BK - Box Of 10 Black Clamp-In Valves for U-Pro Hybrid 2.0**

A box of 10 black clamp-in valves, with each including 1 valve stem, 1 screw and 1 valve cap.  
Nut Torque: 35.4in-lbs  
Screw Torque: 12.39in-lbs

**6-273 - Box of 10 Clamp-In Valves for Cub Sensor**

Nut Torque: ?Nm  
Screw Torque: ?Nm

**6-273-YBK - Box of 10 Graphite Clamp-In Valves for Cub Sensor**

Nut Torque: ?Nm  
Screw Torque: ?Nm

**6-284-BK - Box of 10 Replacement Clamp-In Valves for Sysgration Tesla Sensor**

Clamp-in valve, with each including: 1 Valve Stem, 1 Nut, 1 Rubber Grommet, 1 Screw, 1 valve Cap and 1 valve Core. This valve is suitable for use with Sysgration Tesla sensors.  
Nut Torque: 53.1in-lbs  
Screw Torque: 26.55in-lbs

**6-284-BS - Box of 10 Replacement Clamp-In Valves for Sysgration Tesla Sensor**

Clamp-in valve, with each including: 1 Valve Stem, 1 Nut, 1 Rubber Grommet, 1 Screw, 1 valve Cap and 1 valve Core. This valve is suitable for use with Sysgration Tesla sensors.  
Nut Torque: 53.1in-lbs  
Screw Torque: 26.55in-lbs

**6-437-1 - Box of 10 Silver Clamp-In Valves with double seal cap for Schrader Faraday**

Nut Torque: ?Nm  
Screw Torque: ?Nm

**6-437AL - Box of 10 Silver Clamp-In Valves for Schrader Faraday**

Nut Torque: 35.4in-lbs  
Screw Torque: 12.39in-lbs

**6-439 - Box of 10 Clamp-In Valves for Dill 5001 Universal Sensor**

Nut Torque: ?Nm  
Screw Torque: ?Nm

**6-439AL - Box of 10 Clamp-In Valves for TRW Ram Sensor**

Nut Torque: ?Nm  
Screw Torque: ?Nm

**6-440 - Box of 10 Clamp-In Valves with 20° bend for ITEC and Volvo Buses**

Nut Torque: ?Nm  
Screw Torque: ?Nm

**6-502 - Box of 10 Snap-In Valves for REDI Sensor**

Nut Torque: ?Nm  
Screw Torque: ?Nm

**6-504 - Box of 10 Snap-In Valves for FCA/JEEP**

Nut Torque: Snap-In  
Screw Torque: 12.39in-lbs

**6-505 - Box of 10 Snap-In Valves for Honda/Accura**

Nut Torque: Snap-In  
Screw Torque: 12.39in-lbs

**6-507 - Box of 10 Snap-In Valves for Toyota with stepped screw**

Nut Torque: Snap-In  
Screw Torque: 12.39in-lbs

**TPMS-416 - Box of 10 Clamp-In Valves for Schrader Sensor**

Nut Torque: ?Nm  
Screw Torque: ?Nm

**TPMS-416AL - Box of 10 Clamp-In Valves for Schrader Sensor**

Nut Torque: ?Nm  
Screw Torque: ?Nm