

# 599SC DIGITAL | ANALOG KITCHEN SCALE INSTRUCTION MANUAL

#### FEATURES:

- · Dual LCD Display and Pointer with Backlight
- Touch Sensory Operation
- · Loading Capacity: Max 5000g / 11 lbs
- Graduation Increments: ±1g / 0.05oz

- Auto Off Feature
- · Overload and Low Battery Indication
- Tare Weight Function
- 3 x AAA Batteries Included

Thank you for purchasing the BIOS Professional Digital / Analog Kitchen Scale. Please read all operating instructions carefully before use. This electronic scale is a precision instrument; with normal care and proper treatment, it will provide years of reliable service.

#### PRECAUTION:

This scale is designed for weighing in the kitchen. Place the scale on a hard and flat surface.

Do not put or store any object on the scale platform when not in use.

## 1. Usage and Set up:

- · Insert 3 x AAA 1.5V batteries and the LCD will show all values for 5 seconds and then automatically turn off.
- · Press ON to turn on the scale.

#### 2. Unit:

 Press the button on the bottom of the scale to switch units between grams and ounces.







### 3. Tare Function:

























NOTE: Under the "Tare Weight" function, the total weight cannot exceed the capacity of the scale.

#### 4. Trouble Shooting:

In case of		Display	Action
Overloading			Reduce ingredients' weight
Low Battery		Lo	Replace batteries
The indicator not ret	urning to zero	too.	Rest Product: Remove the batteries and then insert

## ONE YEAR WARRANTY:

If this product proves to be defective in material or workmanship within one year of purchase, please return it to the address below. It will be repaired or replaced without charge upon receipt of the unit prepaid. Please include return ocurier or best return method if unit is not declared defective. Please include your full name, address, daytime phone number or email address.

■ MANUFACTURED BY / FABRIQUÉ PAR :

THERMOR LTD.
16975 LESLIE STREET
NEWMARKET, ON L3Y 9A1
MADE IN CHINA / FABRIQUÉ EN CHINE
WWW.BIOSMEDICAL.COM