

L P U
S

ST. MORITZ



COMPOSITION

80% wool
20% polyamide

COLOUR FASTNESS TO LIGHT

Note 5
UNI EN ISO 105-B02

PILLING

Note 3
UNI EN 1512434 0


MARTINDALE

80.000 rubs
UNI EN ISO 12947-2

FIRETEST


EN 1021-1
EN 1021-2
A.652(16)

CARE




NOTES

Slight differences in colour may occur



LITTLE BLAKE



COMPOSITION

46% cotton
10% linen
28% acrylic
10% polyester

**COLOUR FASTNESS
TO LIGHT**

Note 5
UNI ENI ISO 105-B02

PILLING

Note 4-5 @ 2.000
UNI ENI ISO 12945-2

MARTINDALE









30.000 rubs
UNI ENI ISO 12947-2

CARE



NOTES

Slight differences in colour may occur



REGAL



COMPOSITION

100% cotton

**COLOUR FASTNESS
TO LIGHT**

light color: note 3-4
dark color: note 4
EN ISO 105-B02

MARTINDALE


100.000 rubs
UN ENI ISO 12947-2

CARE




NOTES

Slight differences in colour may occur



CAPRI



COMPOSITION

100% linen

COLOUR FASTNESS

TO LIGHT

Note 6

UNI EN ISO 105-B02

PILLING

Note 3/4

UNI EN ISO 12945-2

MARTINDALE


30.000 rubs

UNI EN ISO 12947-2

FIRETEST















BS 5852:1979 PART 0

CARE



NOTES

Slight differences in colour may occur



bolzan
www.bolzanletti.it

**spencer
interiors**

spencer interiors
www.spencerinteriors.com