

Thank you for your purchase. A lot of time and effort goes in to every one of my machines to both make them easy to use and allow you to produce exceptional tattoos, your satisfaction with this new machine is very important to me. As the original owner of this machine you are given a 1 year warranty on all parts and labor. Shipping costs will be assessed on a case by case basis. This machine is a tool, although a lot of thought and craftsmanship has gone in to designing this machine to be low maintenance some steps are required to keep it running at it's best.

CARE INSTRUCTIONS;

-Method Voltages. -Lining 7.5-8v's Shading 6.5-7

-Big Can- shading 7-7.6 volts

Micro-liner- lining 6-7 volts.

- All of my rotaries are intended to be used with a single wide "rotary" rubber band. Thinner bands will roll out of place. On Micro-liner models the band goes around the rear binding post and sits in the grooves made for it.

- Don't oil your machine for the first month of use. When you begin your oiling schedule put one drop of oil on the bearing and the friction point where the cam rod meets the a-bar, run machine then wipe off excess. Do this once a week.

- Inspect o-rings. Make sure they are in place and undamaged. If excessive noise or vibration occurs adjust o-ring on a-bar.