



- 2 Using the white insulating dough, create a thin strip that is roughly the same size as the crown base.
- 3 Next, using either the blue or the purple dough (or combination of the two) create the jewels and place them on the points of the crown.




4 Attach the strip of insulating dough to the top of the crown base.




5 Next, curve the crown base into a half circle and place the points on top of the white insulating dough, ensuring the doughs touch.



6 Insert an LEDs to light the crown. Be sure to place the longer LED legs into the base as well as the red wire from the battery holder. Insert the shorter LED legs along with the black whire into the points of the crown.



**7** Turn on the switch of the battery holder to light up the LEDs in the gold crown!



for additional ideas, recipes and more, go to: squishycircuits.com