

# FRANCK MULLER

## GENEVE

### *INSTRUCTIONS FOR USE V 45 S6 SQT*



## MECHANICAL

### **ATTENTION**

Completely wound, this watch has a power reserve of 168 hours.

### *Setting the watch*

**IMPORTANT :** Unwind the winding crown **1** before making any adjustments

#### **1) Winding the watch :**

Wind your watch by turning the crown **1** in position **2**.

#### **2) Setting the time :**

With help of crown **1** in position **3**, turn the hands to the time wanted and push the crown **1** in position **2** once the adjustment is done.

**IMPORTANT :** Wind the crown **1** after the adjustments are finished.