

FRANCK MULLER

GENEVE

INSTRUCTIONS FOR USE V 45 T GRAVITY CS



TOURBILLON

ATTENTION

Completely wound, this watch has a power reserve of 120 hours.

Setting the watch

IMPORTANT : Unwind the winding crown **1** before making any adjustments

1) Winding the watch :

Wind your watch by turning the crown **1** in position **2**.

2) Setting the time :

With help of crown **1** in position **3**, turn the hands to the time wanted and push the crown **1** in position **2** once the adjustment is done.

IMPORTANT : Wind the crown **1** after the adjustments are finished.