LEAKAGE CURRENT METERS & PROBES

TRMS CLAMP-ON LEAKAGE CURRENT METER

MODEL 565

Designed to measure low AC currents, which are typically leakage currents in ground conductors

SPECIFICATIONS

MODEL	_	5	65	
mA AC Current (TRMS, Auto-Ranging)		0 to 600mA		
Resolution 60mA		0.01mA (10μA)		
	600mA	0.1mA (100μA)		
Accuracy	50 to 60Hz	±1.2% of Reading ±5cts		
	60 to 500Hz		ading ±5cts	
500Hz to 3kHz		±3.5% of Reading ±10cts		
AC Current (TRMS, Auto-Ranging)		10 to 100A		
Resolution	10A 100A	0.001A (1mA) 0.01A (10mA)		
Accuracy	50 to 60Hz			
Accuracy	60 to 500Hz	±2.5% of Reading ±5cts		
	500Hz to 3kHz		ading ±10cts	
AC Voltage (TRMS)		0 to 600V		
Accuracy	50 to 60Hz	±1.0% of Reading ±5cts		
	60 to 500Hz		ading ±5cts	
	500Hz to 3kHz	±2.5% of Reading ±5cts		
DC Voltage		0 to 600V		
Resolution		0.1V		
Accuracy		±1.0% of Reading ±3cts		
Resistance		0 to 1kΩ		
Accuracy		$\pm 1.0\%$ of Reading ± 3 cts Buzzer activates <35Ω (0 to 1kΩ)		
CONTINUITY		Buzzer activates	$<35\Omega$ (0 to 1k Ω)	
Frequency (Ayuto-R	anging)	A 11		
Function	0.1.400!!	A-Hz	V-Hz	
Resolution	0 to 100Hz 100Hz to 1kHz	0.1Hz 1Hz	0.1Hz 1Hz	
Sensitivity	TOURZ TO TKRZ	10mArms min	5Vrms min	
Accuracy			• • • • • • • • • • • • • • • • • • • •	
Filter		±0.5% of Reading ±2cts On (50/60Hz only); Off (Full frequency range)		
MAX Sample Rate		100mS		
MECHANICAL		100	лпо	
Jaw Opening 1.10" (28mm)		28mm)		
Maximum Conductor Size		1" (26mm)		
Weight		10 oz (280g) with batteries		
Power Source			Two 1.5V AAA batteries (included)	
ENVIRONMENTAL		1110 1101 7001 00	(indiadou)	
		32° to 104°F (0° to 40°C);		
Operating Temperarture		< 80% RH (non-condensing)		
SAFETY		(112		
Safety Rating		EN 61010-1, EN 61010-2-032, 600V Cat. III		

PRODUCT INCLUDES

(2) color-coded 5 ft test leads, carrying case, batteries and a user manual.





Jaw Opening: 1.10" (28mm) Conductor Size: 1" (26mm)








FEATURES

- Check for leakage and locate insulation breakdowns on live circuits
- Measures leakage current down to 0.1mA with up to 10µA resolution
- Measures current up to 100Arms
- Measures up to 600Vac/pc
- Measures Hz on either V or A inputs
- Measures resistance and continuity
- · Hold feature freezes value
- MAX feature keeps track of highest measured in-rush value
- Zero button ideal for measuring relative values
- Filter to isolate 50/60Hz fundamental from harmonics
- Compatible with VDE 0404
- · Backlight LCD display



CATALOG NO. DESCRIPTION

Clamp-on Leakage Current Meter Model 565 (TRMS, 60mA, 600mA, 10A, 100A, 600VAc/DC, Hz, Ohms, Continuity)



2117.56