



# **ASSEMBLY INSTRUCTIONS**

This product is compatible with MB1178 Bobbed Replacement Bed for Jeep Gladiator (both steel & aluminum versions)



motobilt.com | 334-219-2333





Button Head Screw 1/4"-20 x 3/4" SS Qty 6 Flat Washer 1/4" Qty 6

Nylock Nut 1/4"-20 Qty 6



**STEP 1** 

Loosen & remove the front two lower fasteners that secure the Fender to the Bed. This hardware will be reused. Starting on the Driver Side front, loosen the fasteners that secure the fuel supports to the inner wall of the bed to create a gap between the fuel support plate & the vertical inner wall.

You do NOT need to the remove these fasteners, only create a gap of approximately 1/4".



### **STEP 2**



Position MB1216-01 with the long flange facing inwards & the slots facing UP.


With the gap created in STEP 1, slip MB1216-01 between the Fuel Support Plate & the Inner Vertical Wall.

Line up the small holes of the short flange on MB1216-01 behind the existing holes for the Fender.





**STEP 3** 



Replace the two outer fasteners through the fender, bed & new aluminum inner fender.

Tighten the two outer fasteners.

Tighten the two inner fasteners securing the Fuel Support Plate, with the new aluminum inner fender sandwiched in between.



### **STEP 4**

Moving to the Driver Side rear, loosen & remove the two fasteners that secure the Fender to the Bed.

These fasteners will be reused.

Temporarily position & fasten MB1216-02 using the outer two fasteners.





# **STEP 5**



Using a marker, mark the positions of the holes on the inner flange (two locations).

REV: 0

Another view showing the marking of the two holes.





## **STEP 6**



Using a 9/32" drill bit, drill the upper marked hole through the Bed.

Drill the lower hole through the Bed.





**STEP 7** 



Using the supplied 1/4" Button Head Screws, install the fastener through the Bed & the new aluminum inner fender with the round head of the fastener on the inside of the

Reinstall the outer fasteners through the Fender, bed & new aluminum inner fender.

Tighten fasteners.



### **STEP 8**



Installation on the Passenger Side is similar, except you will drill two additional holes for MB1216-03.

