



# PS-100 PNEUMATIC POSING STOOL SPARE PARTS LIST

1



1pc


2



1pc


4

remove the safety cap before assembly



1pc

6



1pc


A



M8

5pc

# PS-100 PNEUMATIC POSING STOOL ASSEMBLY INSTRUCTION



remove the safety cap before assembly

