

Earth testers

MI 3290 Earth Analyser

SET SPECIFICATION



Licence key	GX	GL	GF	GP
Measurement methods				
Ground Z 2-pole	•	•	•	•
Ground Z 3-pole	•	•	•	•
Ground Z 4-pole	•	•	•	•
Single/multi/sweep frequency	•	•	•	•
Wenner 4-pole	•	•	•	•
Schlumberger 4-pole	•	•	•	•
Selective (iron clamp)	•	•		
Stakeless 2-clamps	•	•		
Transient Impulse Impedance	•	•		
HF 25 kHz Impedance	•	•		
Step / Touch	•		•	
Voltage potential	•		•	
Low Impedance 4-point	•		•	
Low Resistance 200 mA	•		•	
Tower Passive one rod / Flex clamps	•			•
Tower FOP / 1xFlex clamp	GX1			•
Tower FOP / 4xFlex clamp	GX4			Option
Mono Tower FOP / Flex clamp	•			•
Measurement accessory				
Current earth spike, 90 cm, 2 pcs	•	•	•	•
Potential earth spike, 50 cm 2 pcs				
G clamp				
Shielded test lead on reel, 75m				
Test lead on reel 50 m, 3 pcs (black, green, blue)				
Test lead, 5m, 2 pcs (blue, red)				
Set of test probes, crocodile clip and 2m test lead, 4 pcs				
Flex clamp 5 m with 15 m shielded cable,	4 pcs (GX4) / 1 pce (GX1)			1 pce
Iron clamp, 2 pcs	•	•		
Kelvin clamp with 2,5 m cable, 2 pcs	•		•	
Step Contact Meter Measuring Set	•		•	

Duncan Instruments Canada Ltd.

216 Rivermede Road, Units 1 & 2, Concord, Ontario L4K3M6 Canada Tel.
416-742-4448 - Fax 416-749-5053
<http://www.duncaninstr.com> - E-Mail: sales@duncaninstr.com