

SLIK® デジタルバランス プロ

取扱説明書

このたびは、スリック製品をお買い求めいただきまことに ありがとうございます。ご使用前にこの説明書をよくお読みいただき 正しく、十分に性能を生かしてお使いください。お読みになったあとは 必ず保管し、わからないときには再読してください。

⚠ 注意 このマークは取扱いを誤った場合、人が傷害を負ったり 物的損害の発生が想定される内容です。

◇ 禁止 このマークは禁止 (してはいけないこと) 内容です。 説明にしたがい事故のないようお使いください。

外形寸法(パンハンドル除く)

仕様

長さ 130 mm 幅 120 mm 高さ 118 mm

ティルト角度 上向き約90/下向き約90


質量(パンハンドル含む) 1.300 g 固定方式 クイックシュ一式 使用温度範囲 -15C~+50C

各部名称

K120-2

English instruction in reverse side.

カメラシュー カメラシュ一固定ツマミ パンハンドル アジャスター パンハンドル



持ち運びのとき

カメラは三脚から外して持ち運んで

ください。カメラの落下、使用者や

周囲の人へのケガ、物損等を起こす

可能性があります。

◎ 禁止


※三脚用のレベラーは水平調整のめやすです。 カメラ内蔵のレベラーとは精度が異なります。

機材の取り付けと セットアップ



カメラの取り付け、ハンドル、ツマミ、 レバー類のロックは確実に行って、 落下や転倒を防いでください。

カメラシュー



U3/8"カメラネジは溝の端にずらすと取り外せます。 必要でない場合は取り外して保管してくださいください。

搭載する機材




この製品は、5kg位までの機材を 載せるように作られています。 これ以上の機材は載せないでください。 また、5kg以下のものであっても 重心位置によりバランスの取りにく いものもあります。 十分に注意してお使いください。


本機にスプリングによるバランサー (補助機構)が内蔵されています。 バランサー機構は搭載機材の総質量 が、1kg~2kgの間で良好に働き

この範囲外ではバランサー機構の 性能を十分発揮できない場合があ ります。

バランサー対応質量

パンハンドルの取り付け





梱包材の中に同梱されているパンハンドルを次の順序で雲台にセットしてください。 1.パンハンドルアジャスターをゆるめます。 2.パンハンドルのローレットが隠れるようにアジャスターに差し込みます。


3.パンハンドルアジャスターを締めて、ロックします。

三脚への取り付け方



パンロックレバーをしめてから、雲台の三脚取り付けネジと三脚の雲台取 り付けネジを合わせ、雲台座をまわしてねじ込みます。

大ネジ(3/8"インチ)の三脚を使用する場合は、ネジアダプターを取り外 して使用してください。




パンハンドルをにぎり、矢印の方向に回し、増し締めを行ってください。 この時、ハンドルに過度の衝撃を与えることはおやめください。 雲台本体やハンドルが破損する恐れがあります。

フロントマーク

ビデオボス取り付け穴

雲台の使い方



ティルトストッパーをゆるめると前後にティルト パンストッパーをゆるめるとパンニングできます。

カメラシュー固定ツマミを矢印の方向へ1回転 程度回します。

シューストッパーを押しながらカメラシューを 矢印の方向へ引き抜きます。

機材の取り付け方




カメラシューのフロントマークを機材の前側にし て、機材の三脚取り付けネジにカメラネジを合わ せてからコインなどを使い、しっかりとねじ込み ます。使用する機材ヘビデオボス取り付け穴があ る場合は、ビデオボスを合わせてからカメラネジ をねじ込んでください。

シューストッパーを押しながら、カメラ台にカメラシューを矢印の方向から 奥まで、さし込んでください。シューストッパーを放すと、カメラシューは 外れなくなります。バランスの良い位置でカメラシュー固定ツマミをしめて 固定してください。

雲台の水平調整

お手入れ



脚の長さを調整し、水準器の中の気泡が赤い円に入るように調整してくださ い。次にカメラシューを前後にスライドさせて、機材の前後重量配分を調整 してください。

脚の水平調整、機材の前後重量配分の調整が成されていない状態で、パンス トッパーをゆるめないでください。機材の自重で雲台が回転して危険です。

◇ 禁止



•よごれたときには、中性洗剤をやわらかな布につけてふいてください。 その後、きれいな乾いた布でふいてください。

•三脚や雲台各部へのオイル・グリス等の補充は絶対にしないでください。 破損、故障の原因となります。

可動部の動きが悪くなってきた場合は、お買い求めの販売店または アフターサービスへご依頼ください。

•火に近づけないようにしてください。 夏など高温になる車内などに長時間放置しないでください。 したがって本期間中は修理をお受けいたします。

インターネット・ホームページ http://www.slik.co.jp/

本製品の補修用性能部品は製造中止後5年を目安に保有しております。

*改良のため、お断りなくデザイン、仕様を変更することがありますのでご了承ください。 ©2014 SLIK CORPORATION



DIGITAL BALANCE PRO

Operating Instructions

Thank you very much for choosing SLIK Pan Head.

SLIK Corporation has designed your pan head to be a sturdy, rugged, dependable product that will provide you with many years of

Please take a few moments to read this operating instructions carefully before use so that you can take full advantage of your Pan head's many fine features. Retain this operating instruction in case you might want to refer back to it.

Caution

This caution icon refers to information pertaining to important safety procedures in preventing injuries, or damages which may occur as a result of mishandling this product.

O Prohibition

This prohibited icon refers to information pertaining to prohibited con-tents. Please refer to instructions closely to avoid accidents.

Specification

130 mm Length 120 mm 118 mm 1.300 g -15C~+50C


Wedth Height Weight Operating temp

Tighten the pan lock lever.

How to attach to tripod

The head screws into the top part of a tripod.

When you use 3/8 inch screw, remove a thread adapter first.




Turn the pan handle and make sure the head is attached to a tripod firmly. Do not turn the pan handle by force. This caused a damaged on the head, the pan handle and other part.

Components

K120-2

Quick release plate Quick release lock knob Pan handle Pan handle

Quick release plate



Equipment that can be




This product has been designed to handle equipment weighing under 2 kgs (4 lbs 6 oz). Do not

Some equipments weighing under 2 kgs (4 lbs 6 oz), such as long lenses, may not balance well due to its weight distribution. In such case use a larger tripod.

This product adopted balancer system operated by coil springs. The balancer system is optimized a camera weighing between 1kg and 2kg.

If your camera weight is out the range, the balancer system may not perform well.


Using the pan head




Loosen the Tilt lock knob to move forward and backward

Loosen the panning lock knob for panning.

Attaching a Camera



Turn the Quick release lock knob once and remove the Quick release plate to direction of arrow in picture.



Set the front mark of a the quick release plate before your video camera side and then, set a camera screw fitting the tripod attachment screw of a video camera by using coin, etc.

It thrusts firmly. When a retractable positioning pin attachment hole is in the equipment, please screw in a camera screw after uniting a video boss.

Release stopper

Setting up

⚠ Caution

tightened.


To prevent accidental equipment

fall or tripod tipping over making

sure all levers, knobs and handles

on the tripod are securely

Leveller




Install the Pan handle

OProhibition

Carrying the Tripod

Carrying a tripod with a camera left on can result in unexpected accidents.


We therefore, recommend you to remove your camera while you are carrying the tripod.



Set the pan handle (included) as follows. 1.Loosen the pan handle adjuster.

2. Put the pan handle into the pan handle adjuster fully.


3. Tighten the pan handle adjuster.



Please insert the Quick release plate in a Camera platform from the direction of an arrow while you are pushing the Release stopper. When the Release stopper is released, a Quick release plate stops movina

Please fix the Quick release knob in total in the good position of balance.

How to adjust a level of pan head



Adjust each leg length to put an air bubble into red circle. Then adjust the quick release plate where a whole tripod is well balanced. Do not loosen pan stopper until adjusting leg length and the quick release

plate. This caused a head turns their own weight and can be damaged.

Care of the tripod

- DO NOT apply any grease or oil to this product.
- Clean with a mild detergent and a soft cloth only.
- DO NOT use close to flame. Avoid extreme heat.



Slik Corporation reserves the right to make changes in design and/or improvements on the products without any obligation and ad vanced notice.

SLIK CORPORATION

853 Kayama, Hidaka City, Saitama 350-1231, Japan ©2014

Printed in Japan