SUZUKI


TYPE: Jimny

MODEL: SN413, FJB33V

YEAR: 1998 ON

DETAIL: 3 Door 1.3L Hard Top / Soft Top, 1.5L TDi GJ 2018 ON





7. Ensure bushes in both arms are identical. (Lay arms together to verify)

8. Re-install arms to vehicle, and perform wheel alignment. (Check tension of bolts after 500km)

This template is suitable for 50mm Lift.

For lifts other than 50mm, your vertical line
may be positioned different to this template, in such a case,
use your vertical line and disregard this template.

Not suitable for vehicle lifts greater than 80mm.