

STOP USE AND RECALL NOTICE – End User



Immediate Action Required

SL227 PILOT Horizontal Static Line Traveler

Sayfa Group are the manufacturers of the TRAVEL8 and PILOT fall arrest system which has been purchased by your company.

This safety alert relates to the SL227 PILOT Traveller issued within the period from June 2018 to August 2019. Due to a manufacturing issue, there is a concern that the SL227 Traveler could dislodge from the cable when in use.

You are required to immediately remove the PILOT Traveller/s from service as notified by your Installer and return these units to your system installer who will then arrange for the units to be checked and exchanged immediately.

Although the defect seems to be very limited, SAYFA GROUP recognise the serious consequences of severe injury or death in the event of failure.

We apologise for the inconvenience caused and thank you for your support in ensuring the highest levels of safety in the workplace.

If you require assistance, please contact your Height Safety System Installer or Sayfa Group:

Email : technical@sayfa.com.au (use the following subject line : SL227 PILOT SAFETY ALERT)

Telephone: 03 8727 9000.

(explain to operator that your call relates to the SL227 PILOT TRAVELLER SAFETY ALERT.

Batch Numbers of units related to the recall. (June 2018 – August 2019)

1450-26112-01 to 08

1450-28386-01 to 08

1450-28735-02 to 08

1450-40614-01 to 08

SAYFA GROUP

technical@sayfa.com.au

DATE: 28/10/2019