
ASSEMBLY INSTRUCTION ITEM NO: 194S9269DB/CR-1 CHAIR

LEGS ARE STORED IN THE BOTTOM OF THE SEAT, PLEASE TAKE OUT FOR ASSEMBLY.

NO.	PARTS LIST	QTY	DESCRIPTION	NO.	HARDWARE LIST	QTY	DESCRIPTION
A		1	CHAIR	В	¢106*70mmH	4	WOODEN LEGS



MADE IN VIETNAM