

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch

198 Ke Zhu Road, Science Park, Economic & Technology

Development Zone, Guangzhou, China

Tel: +86-20-8215 5555 Fax: +86-20-8215 5189 Ref No: SL92019290141801 Issued date: September 15,2020

## **Certificate of Conformance**

Manufacturer: CORTINA NV

Style Name: CADOR

Buyer/Brand: SAFETY JOGGER

It is confirmed that the submitted said product meets the performance requirements of ASTM Specification F2413-18 as tested in accordance with ASTM Test Methods F2412-18a.

The safety hazard(s) tested are listed below:

Safety Hazard(s)	Report Number	Issued Date	Test Result
Impact Resistant (I)	SL92009289736101FW	September 04,2020	Pass
Compression Resistant (C)	SL92009289736101FW	September 04,2020	Pass
Static Dissipative Performance (SD 10)	SL92009289736101FW	September 04,2020	Pass
Puncture Resistance Plate* (PR) - Puncture Resistance	SL92009289736101FW	September 04,2020	Pass
Puncture Resistance Plate* (PR) - Flexing	SL92019290141801FW	September 15,2020	Pass
Puncture Resistance Plate* (PR) - Corrosion	SL92009289736101FW	September 04,2020	Pass

This Certificate of Conformance must be used together with the associated test report(s) listed above.

Ren Yudong, Edison

**Technical Manager** 

Softline laboratory

