

TEST REPORT

 Report No. :
 HL30014/2023

 Page :
 1
 of
 2

 Date :
 MAR. 17, 2023

Krall+Roth Asia Pte Ltd

4 Chang South Lane, #05-04 Nan Wah Building, Singapore 486127

| The following merchandise | was submitted and identified by the applicant | as: |
|---------------------------|---|-----|
| Product Description: | 4780 | |
| Country of Origin: | Taiwan | |

We have tested the submitted sample(s) as requested and the following results were obtained:Test Requested:---See following sheet(s)---Test Method and Result:---See following sheet(s)---

Date of Receipt:

MAR. 01, 2023

Testing Period:

MAR. 01, 2023 ~ MAR. 17, 2023

Signed for and on behal SGS Taiwan Ltd. Iris Huang Manager

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com.tw/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instruction, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced, except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司

新北市五股區(新北產業園區)五工路 127號 +886 (02) 2299-3279 f+886 (02) 2299-2920 No.127, WuKung Road, (New Taipei Industrial Park) Wuku District, New Taipei City, Taiwan



TEST REPORT

 Report No. :
 HL30014/2023

 Page :
 2
 of
 2

Test Results:

Abrasion Resistance (12kpa) (ISO 12947-2:2007 - Martindale tester)


Number of rubs

Over 150,000

Note:

- 1. As per client's request, test specified side only.
- 2. The content of this report is invalid if it is not presented as the entire report.
- 3. The test was conducted at SGS Taiwan Ltd. Textile Laboratory.





--- End of Report ---

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com.tw/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instruction, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced, except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

新北市五股區(新北產業園區)五工路 127號 +886 (02) 2299-3279 f+886 (02) 2299-2920 No.127, WuKung Road, (New Taipei Industrial Park) Wuku District, New Taipei City, Taiwan