

7/19/16

Black Claw

Re: Lot# 002-014

Dear Black Claw

Enclosed are the results of analysis for samples received by the laboraory on 7/15/2016  
The results related only to the samples included in this report.  
The project was assigned a report number of 86342

If you have any questions concerning this report, please feel free to contact us.

Sincerely,

A handwritten signature in cursive script that reads "C.Y. Chan".

CY Chan  
QA Officer

# Laboratory Report

Black Claw

Project Name: Comprehensive Lot Test  
 Project Location:  
 Project Number: Lot# 002-014  
 Date Sampled:  
 Date received: 7/15/16

Report Number: 86342  
 Report Date: 7/19/16

## AOAC 974.02

Analyte: Total Lead (Pb) in solder quantitation by FLAA

Field ID	Lab ID	Result mg/Kg(ppm)	Detection Limit mg/Kg(ppm)	Result (%)
Lot# 002 - 9MLT	K6472	ND	75	ND
Lot# 003 - S9L	K6473	785	398	0.08
Lot# 004 - 11MAG	K6474	ND	126	ND
Lot# 005 - 8HL	K6475	148	128	0.01
Lot# 006 - T3L	K6476	ND	466	ND
Lot# 007 - 10HL	K6477	325	125	0.03
Lot# 008 - S9L	K6478	412	228	0.04
Lot# 009 - 15MAG	K6479	80	70	0.01
Lot# 010 - S9L	K6480	530	457	0.05
Lot# 011 - S7L	K6481	ND	940	ND
Lot# 012 - 7MLT	K6482	ND	146	ND
Lot# 013 - 7BPM	K6483	ND	127	ND
Lot# 014 - S7L	K6484	ND	435	ND

ND = Not Detected or less than Detection Limit

### Quality Control Report: Lead (Pb)

	Measured Conc. (mg/L)	Expected Concentration (mg/L)	Recovery (%)	Lower Limit	Upper Limit	
<b>PB1607191</b>						
ICV	4.9	5.0	98%	80%	120%	PASS
Prep Blank	0.3	0.0	--	0.5 mg/L	--	PASS
LCS	3.0	2.8	109%	70%	130%	PASS
QC Blank	0.0	0.0	--	0.5 mg/L	--	PASS
QC Check	5.0	5.0	101%	80%	120%	PASS
QC Blank	0.0	0.0	--	0.5 mg/L	--	PASS
QC Check	5.1	5.0	102%	80%	120%	PASS
QC Blank	0.0	0.0	--	0.5 mg/L	--	PASS
QC Check	5.1	5.0	102%	80%	120%	PASS
Calibration $R^2$ :	0.9993	(Lower Limit: 0.990)				PASS

**WYBAST**

Environmental Sciences, Inc.  
2415 SE 11th Ave. Portland Oregon 97214

**CHAIN OF CUSTODY**

Report Number

**86342**

Phone(503) 231-9320 FAX(503) 231-9344

Company <b>Black Claw</b>		Phone [REDACTED]											
Project # <b>Lot # 002 - 014</b>		FAX <b>support@blackclaw.com</b>											
Project Name <b>Comprehensive Lot Test</b>		Purchase Order #											
Site		Report Attention <b>Wesley Brown</b>	Collected By										
Samples: Temperature <b>14</b> On Ice? Yes ( ) No ( <input checked="" type="checkbox"/> )		Turnaround Time: <input checked="" type="checkbox"/> Regular <input type="checkbox"/> 3-5 Business Days											
LAB ID	Field ID	Sampling Date	Sampling Time	Matrix	Container	Volume	NW-TPH-Dx	NW-TPH-GX	NW-TPH-HCID	EPA 8021B (BTEX)	EPA 8270 SIM (PAH)	EPA 8260B	Comments
K6472	Lot # 003 - 9MLT			TAPCO WASTE									
K6473	Lot # 003 - 59L												
K6474	Lot # 004 - 11MAG												
K6475	Lot # 005 - 8 HL												
K6476	Lot # 006 - T3L												
K6477	Lot # 007 - 10 HL												
K6478	Lot # 008 - 59L												
K6479	Lot # 009 - 15 MAG												
K6480	Lot # 010 - 59L												
K6481	Lot # 011 - 57L												
K6482	Lot # 012 - 7MLT												
K6483	Lot # 013 - 7BPM												
K6484	Lot # 014 - 57L												
Relinquished by <b>Wesley Brown</b>		Affiliation		Date <b>7/15/16</b>	Time <b>10:40 am</b>	Received by <b>W</b>		Affiliation <b>WYBAST</b>		Date <b>7/15/16</b>	Time <b>10:24 am</b>	Analysis Requested	
Relinquished by		Affiliation		Date	Time	Received by		Affiliation		Date	Time	Analysis Requested	