
OUTBOARD
145-9/16
135
120-7/8
106-11/16
92-1/2
INBOARD
DC23901
- 1 Req'd. (Glued to Fabric at Lift Strut Fittings.)
DC82461
Wing Inspection Window
-Attach with MS51861-12 (x8)
(Underside of Wing)
DC80541-2
Inspection Window Frame
(Underside of Wing)
DC60863-3
Fabric Reinforcement
(Underside of Wing)
4-1/4
3-1/4
13-3/4
12-3/4
Bottom of Aileron False Spar
DC60671
Grommet
- Located over C/L of Aileron Pulley Bracket (Top-Side of Wing)
DC60863-9
Fabric Reinforcement
- Aileron Hinge passes thru False Spar at this location.
DC15761
Fabric Reinforcement
- 2 Req'd. (Glued to fabric around Lift Strut Fitting.)