

## [injectorcleanup.com](http://injectorcleanup.com)

Customer Name	Injector Cleanup	Injector Manufacturer	Dodge	High Speed Tests				Medium Speed Tests	
Customer Email	sales@injectorcleanup.com	Injector Model	68170238ab	Leak Test 1min @ 50psi	Acceleration Test x3 (cc)	30sec @ 43.5psi #1 (cc)	30sec @ 43.5psi #2	30sec @ 43.5psi #1	30sec @ 43.5psi #1
Customer Phone		Date	3/11/2023						
Injector ID	Ohms	Ultrasonic Cleaning	Leak Test 1min @ 50psi	Acceleration Test x3 (cc)	30sec @ 43.5psi #1 (cc)	30sec @ 43.5psi #2	30sec @ 43.5psi #1	30sec @ 43.5psi #1	
e309f06401	12	Yes	Passed	38	45	45	16	15	
e225f08742	12.1	Yes	Passed	38	45	45	16	15	
e135f09033	12	Yes	Passed	39	47	47	17	16	
e135f09002	12	Yes	Passed	39	47	47	17	16	
e135f09004	12	Yes	Passed	46	55	54	20	20	
e135f09032	12	Yes	Passed	42	49	51	18	18	
e225g10602	11.9	Yes	Passed	39	47	46	16	16	
e225f06712	12.2	Yes	Passed	38	46	45	15	15	

Note anomaly detected, switched ports for 09004 and 06712 during high speed test. Results still stand as anomaly travelled with injector.

