


Product Safety Recall



0615

0715

1015

1215

Buzzy Bee pull along toy

All Buzzy Bee pull along toys with batch numbers 0615, 0715, 1015 and 1215.

Other batch numbers are not affected.

Defect: The back wheel can come loose and detach.

Hazard: If the rear wheel detaches it poses a potential choking hazard to young children.

What to do: Stop your children from playing with Buzzy Bee toys showing these batch numbers and store safely until further notice. We are working with the manufacturer on the replacement of Buzzy Bees.

If you have an affected Buzzy Bee please register your contact details and batch number of your Buzzy Bee so that you can be contacted when replacement stock is available.

Contact details: For more information and registration for a replacement Buzzy Bee
phone: 0800BUZZEE (0800 28 99 33)
email: buzzybee@bbrecall.co.nz (to register for a replacement Buzzy Bee and for more information)

New Zealand Importer/Distributor

Brand Protocole Limited
14 Andrew Baxter Drive, Airport Oaks, Mangere, Auckland 2022
New Zealand
+ 64 9 255 5860

See www.consumeraffairs.govt.nz for
other New Zealand consumer product recalls

Issued: March 2016