

**Test Report** No.: NBHL2206011877SD-01 Date: JUN. 23, 2022 Page: 1 of 2

QUANTUM SAFETY NETWORK PTE LTD 998 TOA PAYOH NORTH ##03-14/15, SINGAPORE 318993

THIS REPORT IS TO SUPERSEDE TEST REPORT NO.: NBHL2206011877SD, DATE: JUN. 22, 2022.

The following sample(s) was/were submitted and identified by the client as: Sample Description : AL-GARD TOOL LANYARD

Sample Quantity : PLEASE REFER TO THE FOLLOWING PAGE(S)

Item No. : ALG-TL2-10

\*\*\*\*\*\*

Sample Receiving Date : JUN. 15, 2022

Testing Period : JUN. 15, 2022 TO JUN. 22, 2022

Test Requested
Loading Test (As per client's requirement)

Result
See Result

Since the data and / or information above division line of front page is provided by the applicant, the relevant results or conclusions of this report are only made for these data and / or information, SGS is not responsible for the authenticity, integrity and results of the data and information and / or the validity of the conclusion. Testing results only apply to the sample as received.

The declaration of conformity is only based on the actual value of laboratory activity while measurement uncertainty of the results is not taken into account.

Signed for and on behalf of

SGS-CSTC Standards Technical Services Co., Ltd. Ningbo Branch

Ruby Gu

Ruby Gu Authorized Signatory



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="http://www.sgs.com/en/Terms-and-Conditions.aspx">http://www.sgs.com/en/Terms-and-Conditions/Terms-and-Conditions for Electronic Documents at <a href="http://www.sgs.com/en/Terms-and-Conditions/Terms-and



**Test Report** No.: NBHL2206011877SD-01 Date: JUN. 23, 2022 Page: 2 of 2

## **Test Conducted:**

## Loading Test (As per client's requirement)

Number of Tested Samples:	1 Piece
Number of Controlled Sample	1 Piece
Test Procedure:	<ol> <li>Visual check the sample for any imperfection prior to testing.</li> <li>Load the sample with 12kg weight as per client's specification.</li> <li>Remove the load from the sample after 24 hours.</li> <li>Inspecting the sample for any damage.</li> </ol>
Test Result:	No cracking or visual change was found on the tested sample.

Remark: This report updates the report template.

## Sample Photo:



SGS authenticate the photo on original report only

\*\*\*End of Report\*\*\*



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sss.com/en/Terms-and-Conditions.aspx.and-for-electronic for-main documents.">https://www.sss.com/en/Terms-and-Conditions.aspx.and-for-electronic for-main documents.</a>
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document ladvised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instructions, if any. The Company's sole responsibility is to its Client and this document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery clasification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.