


Removing the FRONT STONE # 218877 from Solo Plus and Excel Boilers

First, make sure that the silicone sealant that is applied around the outside edges of the stone is cut and/or removed. Clean the surrounding steel surfaces as much as possible. On Scandtec Solo Plus boilers remove the upper hinge and latch bolts. After the surfaces are clean and free of the bolt obstructions, using a "Superbar" pry bar or other like pry bar as shown, gently pry the bottom of the stone toward the front of the boiler until it begins to jam. Next, reach through the loading door and press with a hand (gentle tapping with a rubber mallet may also work) on the top of the stone to move the top of the stone outward. By alternating between pushing the top out and prying the bottom out, the stone comes out quickly and easily.



<u>ا من سیحی میں معلمی میں معلمی</u> Tarm Biomass = 4 Britton Lane = Lyme, NH 03768 = 800.782.9927 = www.tarmbiomass.com