AMERICAN BUTTON MACHINES.

Paint Flaking on Button Makers

Congratulations on the purchase of your new ABM button maker!

This equipment is solid 100% US steel with a painted surface.

Please note, flaking paint from the handle is a normal occurrence with new button machines. The functionality of the new button maker is not affected and it will decrease with each use over time until the paint is completely removed as in the pictures shown below.



