




Platen Refurbishment & Teflon Coating




Overview

The Mirra Platen assembly is subjected to chemical and process waste material and will wear over time. During maintenance activity and tool failures the platen can become scratched and form imperfections on its surface. These imperfections, over time, can effect the polishing process.



Service

The customer provides core platen. Entrepix will have the part stripped of hardware and remove any OEM grey paint. The surface of the platen will be lapped to a Super Finish of .0005 micro inches Ra (roughness) of All surfaces will be masked then coated with chemical resistive primer and super slick black Teflon.





To Find Out More Or To Place An Order See Our Links Below.

To see more part details on the platen refurbishment service click the our video icon.



To email Entrepix parts or to get additional parts information click icon.



To explore, shop and download part information click icon.



To call Entrepix parts dial or click. icon

