



# 2003 Tiburon Front









Remove Stock Upper Spring Perch

Seperate Bump Stop  
And Dust Boot



If Needed  
Knock Off  
Cap and  
Reinstall After  
Tube is  
Installed



**GROUND CONTROL**  
www.groundcontrolstore.com  
3885 Dividend Drive  
Shingle Springs, CA 95682  
(530)677-8600 fax (530)677-9090